
From: Peter Maddison <pmaddison@kctmo.org.uk>
Sent: 21 January 2016 15:30
To: 'David Collins'; Complaints
Cc: <Cllr.Blakeman@rbkc.gov.uk>; cllr.r.atkinson@rbkc.gov.uk
Subject: RE: Complaint: Safety and Security at Grenfell Tower
Attachments: One BedGrenfell Tower HIUs Dec 2015.pdf

Dear Mr Collins

Please find attached a further report from our Fire Safety Consultant relating to the location of the HIU in the one bed flats.

In addition to this, our Clerk of Works inspects all installations to confirm quality of work and compliance with technical requirements.


I trust this answers your question.

Yours sincerely

Peter Maddison
Director of Assets and Regeneration



t: [REDACTED]
m: [REDACTED]
a: The Network Hub, 292a Kensal Road, London, W10 5BE

 Before printing, please think about the environment

From: David Collins [mailto:david@future-conversations.com]
Sent: 11 December 2015 08:22
To: Peter Maddison; Complaints
Cc: <Cllr.Blakeman@rbkc.gov.uk>; cllr.r.atkinson@rbkc.gov.uk
Subject: Re: Complaint: Safety and Security at Grenfell Tower

Dear Peter,

Thank you for the report. It is much appreciated.

As for the claim you have never implied the HIU could be directly above the fuse box, I have heard that many times from TMO and Rydon people.

In the report your specialist states, "The units do not protrude out into the hallway, they are contained within the cupboard space/area off the hallway". This is not correct for a number of flats. Please could you ask your specialist to re-look at his report in that light.

In your response you do not comment on the safety of the HIUs being fitted directly above the fuse box. To clarify matters, please could you instruct your fire safety specialist to conclude on the safety of such a configuration, as he does not do so in his report.

If you would like me to investigate and report back to you on the flat(s) where the HIU is located above the fuse box (or to investigate and report back on other issues for you) then we would need to raise that as a commercial matter. My company could raise a proposal if you can raise a Purchase Order for the work – and I will check with the Compact about any conflict of interest. Otherwise, please could you ask your people to investigate, respond on the safety or otherwise of such a location, and report back.

Thank you for a copy of the report. I was very grateful to receive it. It is just a shame it was not shared sooner with the Grenfell Tower Compact, to build relationship and trust, or that it was not shared sooner to ensure it is accurate in its entirety.

There are many residents who remain concerned about the safety of the HIU location, so close to their door and their fuse box. Reading the report has given me more peace of mind about the matter, but even I remain cautious and skeptical about the real safety in the event of an unforeseen incident. I suggest the TMO find a way to communicate the safety of the installation to residents.

In summary:

1. Please ask your specialist to re-look at the report in the light of his statement on page 2 being inaccurate for some properties
2. Please ask your specialist to conclude on the safety of the configuration of the HIU directly above the fuse box
3. Please comment on the safety of the HIUs being fitted directly above the fuse box
4. If this location requires further investigation, please instruct your people to carry out such an investigation
5. Please reply with these responses to clarify the situation

Best Wishes,

David

From: Peter Maddison <pmaddison@kctmo.org.uk>

Date: Tuesday, 8 December 2015 at 09:29

To: David Collins <david@future-conversations.com>, Complaints <complaints@kctmo.org.uk>

Cc: "<Cllr.Blakeman@rbkc.gov.uk>" <Cllr.Blakeman@rbkc.gov.uk>, "<cldr.r.atkinson@rbkc.gov.uk>" <cldr.r.atkinson@rbkc.gov.uk>

Subject: RE: Complaint: Safety and Security at Grenfell Tower

Dear Mr Collins

Building Control is an organisation that is independent of KCTMO that checks to confirm that work carried out meets necessary regulations. They have checked the installation of the HIU and confirmed that they are satisfied with our approach.

In addition to this, I have asked our Fire Safety consultant to review the installation. Attached is a copy of his report which confirms that no fire risk has been identified in relation to the location of the HIU in the hallway.

You state in your subsequent e-mail that "There is at least one home where the HIU has been located in the front doorway, directly above the fuse box. This was something I was told by TMO / Rydon could never be done, because it would be unsafe."

I would clarify that I have never said that the HIU would not, or could not be located directly above the fuse box because "it would be unsafe". However, if you would provide me with the address where the HIU has been positioned in this way, and I will arrange for a review by a suitably qualified person.

Yours sincerely

Peter Maddison
Director of Assets and Regeneration



t: [REDACTED]
m: [REDACTED]
a: The Network Hub, 292a Kensal Road, London, W10 5BE

Before printing, please think about the environment

From: David Collins [<mailto:david@future-conversations.com>]
Sent: 03 December 2015 06:49
To: Complaints
Cc: Peter Maddison; <Cllr.Blakeman@rbkc.gov.uk>; cllr.r.atkinson@rbkc.gov.uk; Clare Dewing
Subject: Complaint: Safety and Security at Grenfell Tower

Dear Mr Maddison,

On Saturday 11th July 2015 you agreed in the presence of Councillor Blakeman and Atkinson, to commission an independent fire and safety investigation in to the risks of a HIU located in the hallway for both one and two bedroomed homes. As Chair of the Grenfell Tower Compact I know many residents have concerns about the location of a HIU so close to electrics and a fuse box, with both being located next to the only emergency exit from their home.

The promise made has been reneged upon; you have informed our Councillors and the Grenfell Tower Compact that Building Control will inspect the installations instead. This is not a satisfactory solution. An investigation (not an inspection) carried out by an independent organisation which specialises in fire and safety (which Building Control is not) was promised. Building control check for adherence to regulations, but are not guaranteed to assess if there is risk regardless of whether regulations have been met or not, whereas an independent safety specialist would. Only a full and proper investigation by independent specialists would provide clarity for all concerned. Irrespective of the argument, this is also simply a matter of keeping the initial promise.

I look forward to hearing when the independent investigation is going to happen. The Grenfell Tower Compact would also value being involved and consulted in the selection of the independent organisation, to help with the perception of the assessment being an independent one.

Yours sincerely,

David Collins

This e-mail message has been scanned for Viruses and Content and cleared by **MailMarshal**

DISCLAIMER:

This E-mail and any files transmitted with are intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the System Administrator. This message may contain confidential information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this email.

Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent

those of Kensington & Chelsea TMO Ltd Finally, the recipient should check this email and any attachments for the presence of viruses. Kensington & Chelsea TMO Ltd accepts no liability for any damage caused by any Virus transmitted by this email.

This e-mail message has been scanned for Viruses and Content and cleared by **MailMarshal**

DISCLAIMER:

This E-mail and any files transmitted with are intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the System Administrator. This message may contain confidential information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this email.

Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Kensington & Chelsea TMO Ltd Finally, the recipient should check this email and any attachments for the presence of viruses. Kensington & Chelsea TMO Ltd accepts no liability for any damage caused by any Virus transmitted by this email.

Nominations sought for Mayor's Awards

If you know someone who has made an outstanding contribution to the life of the Royal Borough then nominate them for an award and tell us why they are special.
<http://www.rbkc.gov.uk/mayorsawards>

RBKC Local App

Noticed a streetlight that isn't working? Want to report fly tipping? Use the RBKC Local App to report it, register for it, pay for it.
<http://www.rbkc.gov.uk/RBKCLocal>

The Royal Borough of Kensington and Chelsea.
This e-mail may contain information which is confidential, legally privileged and/or copyright protected. This e-mail is intended for the addressee only. If you receive this in error, please contact the sender and delete the material from your computer.
