From: Claire Williams <clwilliams@kctmo.org.uk>

Sent: 10 June 2015 16:39 **To:** Simon O'Connor

Subject: URGENT URGENT: Grenfell FRA - outstanding items

Simon

I think you could polish this off quickly, don't you?

See you at 9.30 tomorrow.

Claire Williams
Project Manager



t:



a: The Network Hub, 292a Kensal Road, London, W10 5BE

Before printing, please think about the environment

From: Claire Williams Sent: 10 April 2015 17:19

To: Simon O'Connor (<u>Soconnor@rydon.co.uk</u>) **Subject:** Grenfell FRA - outstanding items

Simon

I have gone back through the list, and need just a few more bits.

- The service road/area on the right hand side of this tower block is used by the emergency services to park their vehicles, this area has been handed over to the contractors and is presently under their control. The contractors have stated that the LFB are happy with the current parking arrangements whereby the contractors are using part of the service road/area.
- The fire fighter entry over ride device fitted to the entrance door of this building did not function and release the locking device on the door and open the door. This over ride device allows the Fire and Rescue Service to access the building in an emergency without the use of a key.
- 3 The location of this secondary exit from the basement boiler room area should be emphasised to contractors who are working in this area.

This secondary exit should not be blocked or obstructed at any time, this is internally in the boiler room and externally where the exit leaves the building.

- There is a secondary exit route from the basement boiler room area. It is not known when this hatch was last opened and checked to see that it operated correctly.
- 5 I would recommend that the contractor provides
- 1. The scope of works covering how this cladding? How will the cladding be fixed to the building?

- 2. What fixings will be used?
- 3. The fire rating of the cladding and the fixings?
- 4. The Building Control Officers acceptance of this fixing system and the cladding used?

I hope this is ok.


Thanks

Claire Williams
Project Manager





a: The Network Hub, 292a Kensal Road, London, W10 5BE



This e-mail message has been scanned for Viruses and Content and cleared by MailMarshal

DISCLAIMER:

This E-mail and any files transmitted with are intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the System Administrator. This message may contain confidential

information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this email.

Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent

those of Kensington & Chelsea TMO Ltd Finally, the recipient should check this email and any attachments for the presence of viruses. Kensington & Chelsea TMO Ltd accepts no liability for any damage caused by any Virus transmitted by this email.

This email has been scanned by the Symantec Email Security cloud service.	
For more information please visit http://www.symanteccloud.com	