
From: Claire Williams <clwilliams@kctmo.org.uk>
Sent: 13 July 2015 12:29
To: REED Neil
Subject: Grenfell lift issues

Neil

This is the report from Mike Sapsford of Gerald Honey regarding the outstanding issues:

EXTRACT

I am not sure if you are aware of what the introduction of the new floor numbering system on the lifts has had on the landing indicator displays? At the moment the correct floor numbers are being displayed on the landing indicators, however, the direction arrow and associated 'gong' is 3 floors out of step. Consequently when a lift stops on say floor 20 the arrow and gong sounds on floor 23 although the lift is not at that floor.

I hope this is clearer than information you have had before!

Thanks

Claire Williams
Project Manager



t: [REDACTED]
m: [REDACTED]

a: The Network Hub, 292a Kensal Road, London, W10 5BE

Before printing, please think about the environment

This e-mail message has been scanned for Viruses and Content and cleared by **MailMarshal**

DISCLAIMER:

This E-mail and any files transmitted with are intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the System Administrator. This message may contain confidential information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this email.

Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Kensington & Chelsea TMO Ltd. Finally, the recipient should check this email and any attachments for the presence of viruses. Kensington & Chelsea TMO Ltd accepts no liability for any damage caused by any Virus transmitted by this email.