


South Elevation
1 : 50

- 1 ALUMINIUM FACED INSULATED PANEL (L10 332)
- 2 CERAMIC COATED INSULATED GLASS UNIT (L10 333)
- 3 TOP HUNG IV WINDOW (HIGH LEVEL OPERATED BY TELEFLEX)
- 4 ALUMINIUM CURTAIN WALL (L10 331)
- 5 ZINC SPANDREL PANEL CLADDING - RESIDENTIAL FLOORS (H92 123)
- 6 ALUMINIUM FRANGIBLE GLAZED FIXED UNIT (H92 124)
- 7 ZINC FRANGAN EL FINISH R - CURTAIN WALL FINISHES (H92 125)
- 8 ALUMINIUM FRANGIBLE GLAZED FIXED UNIT (H92 126)
- 9 ALUMINIUM CURTAIN WALL (L10 331)
- 10 ZINC COLUMN CLADDING FIXED TO EXISTING COLUMNS (H92 120)
- 11 ZINC COLUMN CLADDING (H92 120)
- 12 CURTAIN WALL - RECEPTION LOBBY (H11 110)
- 13 RESTRAINT BAR



Key
1 : 200

- NOTE:
1. THIS DRAWING IS COPYRIGHT STUDIO E LLP.
 2. THE CONDITIONS MUST BE IN SCALE FROM THE DRAWING. ALL DIMENSIONS TO BE TAKEN FROM DIMENSION LINES.
 3. WHERE ANY DISCREPANCIES ARE FOUND BETWEEN DIMENSIONS THAT MUST BE BROUGHT FORWARD TO THE ATTENTION OF THE ARCHITECT'S FOR RESOLUTION.
 4. WHERE DISCREPANCIES EXIST BETWEEN REFERENCE OF ASSEMBLY DRAWINGS & DETAIL DRAWINGS, THE LATTER TAKE PREFERENCE.

No.	Date	Description
1	01/05/14	Issues removed



FOR INFORMATION

STUDIO E LLP
ARCHITECTS
www.studioe.co.uk

**GRENFELL TOWER
REGENERATION PROJECT**

Proposed South Elevation

PROJNO: 27/11/13

As indicated ECF

1279 (05) 100 00

DATE: 09/02/13