

Message

From: Bruce Sounes [/O=STUDIO E/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=BRUCE]
Sent: 25/09/2013 17:56:40
To: M.Smith@maxfordham.com; Terry Ashton [Terry.Ashton@Exova.com]
CC: d.campbell@maxfordham.com; Tom Ashton [Tom.Ashton@curtins.com]; Stefano.Strazzullo@curtins.com; Grenfell [Grenfell@studioe.co.uk]
Subject: RE: Grenfell - Site visit tomorrow + some more thoughts
Attachments: 2045B Type A.jpg; 1279-SK089 EMB Option.pdf; 12 11 Grenfell Tower 078.jpg

Matt,

I have quite a bit on my plate and we have undertaken many site visits already. As discussed yesterday I would ideally like to see ceilings removed in the lobbies at ground and walkway levels.

I would like to see the cupboards/stores in the corners of the core, highlighted on my markup but it can wait.

EMB Option.

I've attempted a cleaner option for the EMB office, attached:

- incorporates vented lobbies at M & W+1,
- a secondary exit route for the boxing club, shared with the offices
- steeper accommodation stair with winders in an attempt to align void and edge of core, and simplify the additional structure required.
- Accommodation stair not enclosed and does not exit direct to outside.
- Smoke vent shown extending from above to serve lift lobby. (this will be reflected opposite)

I propose to forward this to Building Control for comment and discuss with the TMO, probably next week.

Smoke Vent

The existing drawings indicate twin ducts, which scale at 600x400. Although we haven't checked the dimension but it appears to correspond to the site photo taken in the adjacent store. See attached.

Terry,

The layout of the boxing needs a bit more thought which I will follow up.

Part B1 mentions 0.4m² vent (800 x 500, say) which is quite large. The clause itself seems to qualify the requirement. Do you have any comments?

4.35 A protected lobby should be also provided between an escape stairway and a place of special fire hazard. In this case, the lobby should have not less than 0.4m² permanent ventilation, or be protected from the ingress of smoke by a mechanical smoke control system.

Regards

Bruce Sounes

For and on behalf of
STUDIO E LLP

Palace Wharf, Rainville Road, London W6 9HN
T [REDACTED] | F [REDACTED] | www.studioe.co.uk

From: M.Smith@maxfordham.com [mailto:M.Smith@maxfordham.com]
Sent: 25 September 2013 13:57
To: Bruce Sounes
Subject: Grenfell - Site visit tomorrow

Afternoon Bruce

I'm going to arrange a site visit for tomorrow to get access to Walkway +1 (ideally with the TMO handyman) so we can begin to assess the offsets etc. We'll also be looking at the void flats to check our pipe runs etc. The areas that you have marked up are also of interest to us.

Would you be interested in attending? I'll be confirming with Claire that keys/sledgehammers/ladders will be available first. It'll be from around 11am for as long as it takes (2-3 hrs?).

Kind regards,

Matt

MAX FORDHAM

42-43 Gloucester Crescent

London

NW1 7PE

T +

F +

maxfordham.com

Max Fordham LLP is a Limited Liability Partnership. Registered in England and Wales Number OC300026
Registered office 42-43 Gloucester Crescent, London, NW1 7PE