
From: Kevin Lamb
Sent: 23 January 2015 15:37
To: slawrence@rydon.co.uk
Cc: Daniel Anketell-Jones; Neil Crawford; Bruce Sounes; Mark Stapley; Rob Maxwell; agrint@rydon.co.uk
Subject: Grenfell
Attachments: 855 C1059 GA Model 18 201C (1).pdf; 855 C1059 GA Model 18 200F (1).pdf

Simon,

Please find attached revised typical windows showing reduced qty of trickle vents as agreed with Neil 14.01.15.

Do we have an update yet on the restrictor requirements? We are currently working on keyed handles to the side hung windows so they cannot be opened unauthorized. It looks like additional restrictors would have to be face applied Jak Loc (keyed)!

Note that we are supplying the panels to the kitchen windows in one piece for your M&E contractors to cut and fit extract vents as necessary.

Regards

Kevin Lamb
Project Designer



T- [REDACTED]
F- [REDACTED]
W- www.harleycurtainwall.com

Head Office
Harley House, Brooklands Park
Farningham Road, Crowborough
East Sussex, TN6 2JD

Email Disclaimer:

This email has been sent by Harley Curtain Wall Ltd. The information in this email is confidential and may be legally privileged. It is intended solely for the addressee. Access to this email by anyone else is unauthorised. If you are not the intended recipient, any disclosure, copying, distribution or any action taken or omitted to be taken in reliance on it, is prohibited and may be unlawful. Any views expressed in this message, are those of the individuals sender, except where the sender specifically states them to be the views of Harley Curtain Wall Ltd. Whilst Harley Curtain Wall Ltd takes reasonable precautions to scan email content for viruses, we cannot give warranties or assurances about the safety and contents of this email including any attachments herewith. It is the responsibility of the recipient to scan the email and any attachments herewith sent for malicious content.