

Riser Request Proforma

Use for 3 meter positions and above

This document is classed as the Client Brief and supports the ongoing compliance to The Construction (Design & Management) Regulations 2015. The information contained in this document has been prepared to the best knowledge of the Client and in accordance with Regulation 4 (4)

Date form completed:	01/10/2016	i.e. 25/10/2015	Dispatcher:	KELLY BRAUND	Name	Contact
Time cut off:	02:00:00	i.e. 15:55	Team:	Thomas Hyatt		
			Supervisor:	Luke Milam		
			Band C:	TONY SMITH		

Property Address (inc numbers) :	Building Name/Number, Street	Town/City	Postcode
	GRENELL TOWER, GRENELL ROAD	LONDON	W11 1TQ

ape location:	Flat Within Building	Eastings	523895	Northings	180970
ct location of cut-off/repair:	FLATS 22 AND 32 SERVICE RISER LEAKING ON JOINT.				

Status of supply :	Disconnected	N/A	If so, please select	Internal/ External ?	N/A	Where?	N/A
	Interim repaired	N/A	If so, please select		N/A	How?	N/A
	Temp repaired	N/A	If so, please select		N/A	How?	N/A
	Other	Other (Non-Compliant)					
Comments	VALVE TURNED OFF						

Supply Material:	Steel	Contract Number:	N/A
Supply Diameter:	4"	WR number:	40011757
Riser Material:	Steel	NRWSA Permit Number:	N/A
Riser Location:	Internal	NRWSA Expiry Date:	N/A
Riser Diameter:	2"	Lane Rental Applicable:	No
Base of riser visible:	Yes	Any Excavation?	No
		Any Excavation >1.2m	N/A

Height of Building:	>40 Meters	Number of Meter Points:	3+
Category of job:	High Rise		
Number of Floors:	23		
Number of Properties affected:	38	Customer Details Collected:	5
MOB Building Contacts:	Not Known	Contact Number:	N/A
Managing Agent:	N/A		
Concierge/Porter:	N/A		
Other:	N/A		
Listed Building:	No	Conservation Area:	No
Any parking restrictions:	No	Comments:	
		Communal heating/hot water available:	Yes, Hot water

H Codes Present at this building. Please see below

H-Code	Description
H15	Cannot position vehicle close to site

Flat No	Occupier Name	Contact Details	Vulnerability Identified	Lettered Gas Off	Main Gas Use	Appliances Used
---------	---------------	-----------------	--------------------------	------------------	--------------	-----------------

CAD00003003/1

CAD00003003_0001

202	N/A		Unknown,	Yes	Cooking	Yes, Hot plate
201	N/A		Unknown,	Yes	Cooking	Yes, Hot plate
192	N/A		Unknown,	Yes	Cooking	Yes, Hot plate
191	N/A		Unknown,	Yes	Cooking	Yes, Hot plate
182	SAOUZIA EL WAHABI		No,	Yes	Cooking	Yes, Hot plate
172	N/A		Unknown,	Yes	Cooking	Yes, Hot plate
162	UNKNOWN		Yes, Young children	Yes	Cooking	Yes, Hot plate
161	N/A		Unknown,	Yes	Cooking	Yes, Hot plate
152	RABIA YAHYA		No,	Yes	Cooking	Yes, Hot plate
151	N/A		Unknown,	Yes	Cooking	Yes, Hot plate
141	N/A		Unknown,	Yes	Cooking	Yes, Hot plate
142	N/A		Unknown,	Yes	Cooking	Yes, Hot plate
132	N/A		Unknown,	Yes	Cooking	Yes, Hot plate
131	N/A		Unknown,	Yes	Cooking	Yes, Hot plate
122	N/A		Unknown,	Yes	Cooking	Yes, Hot plate
121	N/A		Unknown,	Yes	Cooking	Yes, Hot plate
111	N/A		Unknown,	Yes	Cooking	Yes, Hot plate
112	N/A		Unknown,	Yes	Cooking	Yes, Hot plate
102	N/A		Unknown,	Yes	Cooking	Yes, Hot plate
101	N/A		Unknown,	Yes	Cooking	Yes, Hot plate
92	KAREN ABOUD		No,	Yes	Cooking	Yes,
91	N/A		No,	Yes	Cooking	Yes,
82	N/A		No,	Yes	Cooking	Yes,
81	N/A		No,	Yes	Cooking	Yes,
71	N/A		No,	Yes	Cooking	Yes,
72	N/A		No,	Yes	Cooking	Yes,
61	N/A		No,	Yes	Cooking	Yes,
62	N/A		No,	Yes	Cooking	Yes,
51	N/A		No,	Yes	Cooking	Yes,
52	N/A		No,	Yes	Cooking	Yes,
41	N/A		Unknown,	No	Cooking	Yes,
42	N/A		No,	No	Cooking	Yes,
31	N/A		No,	No	Cooking	Yes,
32	AVELINA SHAH		Yes,	Yes	Cooking	Yes,
21			No,	No	Cooking	Yes,
22	SHAHIA SADANI		No,	No	Cooking	Yes,
			,			,
			,			,
			,			,

ditional Comments 118/specific SSRA issues e.g. abusive customers, asbestos present, specific vulnerability

171, - CUSTOMERS DO NOT USE GAS