




Grenfell


New Flat entrance door 112 not marked as FD30 m s fitted no SC





DS on ceiling outside flat 46





Door damaged flat 24

