

Paragraph Number	BSR Reference	Inquiry URN	Description
		{IWS00001636}	Phase 2 Witness Statement of Mariama El Hassani
19	MH/1	{IWS00001628}	Exhibit MH/1 - Photograph of ceiling after a leak
22	MH/2	{IWS00001638}	Exhibit MH/2 - KCTMO repairs log regarding balcony leak
23	MH/3	{IWS00001640}	Exhibit MH/3 - KCTMO repairs log regarding bathroom leak
26	MH/4	{IWS00001634}	Exhibit MH/4 - KCTMO repairs log regarding blocked drainage
28	MH/5	{IWS00001643}	Exhibit MH/5 - KCTMO repairs log regarding broken window
31	MH/6	{IWS00001641}	Exhibit MH/6 - Photograph of broken window
32, 36	MH/7	{IWS00001631}	Exhibit MH/7 - KCTMO repairs log regarding pest infestation
39, 40, 41, 47	MH/8	{IWS00001632}	Exhibit MH/8 - KCTMO repairs log for gas cooker
46	MH/9	{IWS00001635}	Exhibit MH/9 - Photograph of gas pipes inside Hurstway Walk
	MH/10	{IWS00001630}	Exhibit MH/10 - Photograph of gas pipes outside Hurstway Walk