

# THE GRENFELL TOWER INQUIRY

---

## EXHIBIT ZC/3

---

This is the Exhibit marked “ZC/3”  
referred to in the witness statement  
of Shkelzen Canaj

# Defect

JSW11666



J S WRIGHT & CO LTD

Date To Attend 01/06/2017  
Time To Attend 10:00AM - 02:00PM

## Your Job Reference

JSW Job Number 11666  
Contract Number 9497  
Contract Name CLOSED - Grenfell Tower  
Principle Contractor Rydon Maintenance  
Date Defect Received 01/06/2017  
Time Received 11.36  
Priority Routine  
Defect Details bms panel as there is a red light on but no alarms logged

Property Number Plant Room  
Property Address Grenfell Tower, Grenfell Walk, Notting Barns, W11 1TQ  
Contact Name David Hughes  
Contact Number [REDACTED]  
Occupier Contacted? N/A

Date	Recorded By	Comment
15/06/2017 07:51:39	Steve Brown	Defect record closed.
15/06/2017 07:51:30	Steve Brown	The defect will be closed due to the unfortunate fire incident that took place on the 14th of June at Grenfell Tower. No update has been sent to Rydon's.
05/06/2017 08:55:55	Antony Willmott	E-mail has been received @ 17.19 on the 2nd June from Zeni with his engineer report following his appointment to this defect on the 1st June.
02/06/2017 08:25:19	Antony Willmott	E-mail has been sent to Zeni requesting his report following his appointment to this defect on the 1st June.
01/06/2017 11:58:27	Antony Willmott	We have an engineer attending to site on the 1st June between 10-2 for JSW 11665. We will arrange for our engineer to attend to this defect at the same time.

If any of the details are incorrect, please telephone a member of the Aftercare team on [REDACTED] or email [aftercare@jswright.co.uk](mailto:aftercare@jswright.co.uk).



Once the detailed works have been completed and our office receives the Aftercare Engineer's report, you will be emailed with the details of works carried out and clarification that the defect has been closed.

Should you need any further information, please do not hesitate to contact us.

## Work Carried Out

JSW11666



Date	Engineer	Completed	Reason	Work Carried Out	Signature
01/06/2017	Zeni Canaj				
					 8332.png
01/06/2017	Zeni Canaj	No	Further investigation required	Checked the BMS panel and there was a red light but that had been there for months. All the rest of the pumps and the boilers were running fine no low pressure or any other leaks.	Antony Willmott JSW Aftercare Administrator  8303.png

If any of the details are incorrect, please telephone a member of the Aftercare team on [REDACTED] or email [aftercare@jswright.co.uk](mailto:aftercare@jswright.co.uk).

Once the detailed works have been completed and our office receives the Aftercare Engineer's report, you will be emailed with the details of works carried out and clarification that the defect has been closed.

Should you need any further information, please do not hesitate to contact us.