

THE GRENFELL TOWER INQUIRY

EXHIBIT TNG/3

This is the Exhibit marked “TNG/3”
referred to in the witness statement
of Tobias Neville Guise

Grenfell Tower 9497						GREEN HIGHLIGHT - VERY GOOD STANDARD	YELLOW HIGHLIGHT - NOT YET ACTIONED							CALL OUT RISK			POTENTIAL COST OF CALL			DATE RECTIFIED	COMMENTS	
No of inspections	Item Number	DATE OF INSPECTION	BLOCK / FLOOR / PLOT	LOCATION	ISSUE DESCRIPTION / STANDARD	PICTURE	JSW / SUB CONTRACTOR	STATUS	SNAGGED Y / N	COMMISSIONED	HANDED OVER	GOOD PRACTICE	LOW	MEDIUM	HIGH	LOW	MEDIUM	HIGH				
4	1	14/04/2015	1st Floor Flat D	Hall	Hall way above Kitchen entrance- flat ductwork has come apart, please reinstall into the fitting		JSW	1st fix	N	N	N				1		1					
4		14/03/2015	Summary												1		1					
			Please ensure all flex ductwork is pulled tight to avoid noise and flow restrictions																			