



# AlliedProtection

Part of the Lakehouse Group

## INSPECTION & SERVICING CERTIFICATE (Automated Opening Vents)

Tel: 0345 223 2223,  
Fax: 0345 226 2225  
service@alliedprotection.co.uk

Client Name: Kensington and Chelsea TMO  
Property Address: Grenfell Tower 1-206, Grenfell Road, Grenfell Tower 1-206 Grenfell Ro  
Job Number: KCT258358-1  
Date: 15/05/17

Description of works carried out:  
AOV tested, all ok.

### Tests / Checks done

YES / NO / N/A

Actuators working Correctly?

Yes

Clean, Lubricate and tighten all actuators, dampers and louvres?

No

Left Vents In Closed Position?

Yes

Control and Indicating Equipment operating correctly?

Yes

Power Supply test OK?

Yes

Back up Batteries test OK?

Yes

Wiring OK?

Yes

Rain / Wind Sensors tested?

N/A

Interfacing confirmed as working?

Yes

Smoke detectors tested?

Yes

Cause and Effects Tested?

Yes

Cause & Effects arrangements & Checks completed:

Mag lock doors, where fitted, opened on aov activation.

### Comments / Remedial Works required:

Fire alarm system is a detector linked aov with each floor having local vents/dampers with a smoke vent at top of staircase to roof. All lift lobby detectors tested and operated vents. Grd flr community area was not tested as called out to investigate multiple apv failures in other local blocks.

Customer Signature: \_\_\_\_\_

Client/Representative's Name: no client available

Engineer Signature: \_\_\_\_\_

Arrival Time: 12:15

Engineer Name: Barry McAuliffe

Departure Time: 14:15



Head Office : Unit 2, Regent Business Centre, Jubilee Rd, Burgess Hill, W Sussex, RH15 9TL