

EXPRESS

Service Visit Report



Lifts Alliance
Group

Service and breakdown
London & South East
All Other UK Regions

Registered in London No. 147295 and Jersey No. 202575
Registered Office: Chiswick Park Building 5, Ground Floor, 999 Chiswick High Road, Uxbridge

Visit Type Clean
Unit Number H090 + H019
Customer Order No. BRO185956
Site Address

CALLBACK/REPAIR NO.

Misuse (Y/N) ☐ Completed (Y/N) ☒
Accidental Damage (Y/N) ☐ Shutdown (Y/N) ☐

GRANFILL TOWER
GRANFILL ROAD
WIL ITG

Unit Type/Customer Unit Reference L

Customer Name

Maintenance Activity Report (1 as applicable)

	Checked		Serviceable	
	Y	Not Fitted	Y	N
Car Operating Panels				
Car Lighting				
Emergency Alarm Systems				
Hall Buttons / Indicators				
Floor Levels				
Controller / Drive				
Brake				
Machine / Hydro Power Unit				
Overspeed Devices				
Operation of Car Doors				
Car Top				

	Checked		Serviceable	
	Y	Not Fitted	Y	N
Landing Doors				
Counterweight / RAM				
Main Suspension Check				
Pit Area				
Annual / 4 Year Checks				
Door Check				
Suspension Check				
RA Review				
Elec & Mech Check				
Earth Continuity Test				
Brake Check				

Scope of Work & Materials Used (quoting part number where possible)

CARRIED OUT FULL SHIFT CLEAN DOWNS TO BOTH LIFTS
INCLUDING TOP OF CARS + PITS. ALSO CARRIED OUT
A FULL CLEAN DOWN TO DOUBT MOTOR ROOM

Observations

Engineer's Name (Please print clearly)		Employee Number	Arrival Time	Depart Time	Total Site Hours	Travel Hours
Engineer 1	<u>LEE PARRY</u>	<u>0028</u>	<u>8:00</u>	<u>4:00</u>	<u>:</u>	<u>:</u>
Engineer 2	<u>MARK CLEMENTS</u>	<u>0038</u>	<u>8:00</u>	<u>4:00</u>	<u>:</u>	<u>:</u>

Date 31st
To 4 Feb

Customer's Name
N/A

Customer's Signature
N/A

Top Copy: Customer Second Copy: office