

Registered in London No. 147366 and Jersey No. 0008376
Registered Office, Chiswick Park Building 5, Ground Floor, 566 Chiswick High Road, W4 5YF

Service and breakdown
London & South East: [REDACTED]
All Other UK Regions: [REDACTED]

Visit Type

M

CALLBACK/REPAIR No.

Unit Number

PD807174

Misuse

(Y / N)

Completed

(Y / N)

Customer Order No.

H090

Accidental Damage (Y / N)

Shutdown

(Y / N)

Site Address

GRENELL TOWER

Unit Type/Customer Unit Reference

H090

Customer Name

K/C TMO

Maintenance Activity Report (✓ as applicable)

	Checked		Serviceable	
	Y	Not Fitted	Y	N
Car Operating Panel/s	/		/	
Car Lighting	/		/	
Emergency Alarm Systems	/		/	
Hall Buttons / Indicators	/		/	
Floor Levels	/		/	
Controller / Drive	/		/	
Brake	/		/	
Machine / Hydro Power Unit	/		/	
Overspeed Devices	/		/	
Operation of Car Doors	/		/	
Car Top	/		/	

	Checked		Serviceable	
	Y	Not Fitted	Y	N
Landing Doors	/		/	
Counterweight / RAM	/		/	
Main Suspension Check	/		/	
Pit Area	/		/	
Annual / 4 Year Checks				
Door Check				
Suspension Check				
RA Review				
Elec & Mech Check				
Earth Continuity Test				
Brake Check				

Scope of Work & Materials Used (quoting part number where possible)

LIFT SHAFT CLEANDOWN DONE BY Unique.
New Hinges Required for panel door TLM
3off.

Observations

Various HANGER ROLLER + pick up rollers
require changing.
Unique due to come back on 6 th March to do
Another CLEAN DOWN.

	Engineer's Name (Please print clearly)	Employee Number	Arrival Time	Depart Time	Total Site Hours	Travel Hours
Engineer 1	D SWALEY	55029	:	:	:	:
Engineer 2	J HALE		:	:	:	:

Date: 15/11/17	Customer's Name:	Customer's Signature:
----------------	------------------	-----------------------

Top Copy: Customer Second Copy: Office