

EXPRESS

Service Visit Report



Lifts Alliance
Group

Registered in London No. 147366 and Jersey No. 0008376
Registered Office, Chiswick Park Building 5, Ground Floor, 566 Chiswick High Road, W4 5YF

Service and breakdown
London & South East: [REDACTED]
All Other UK Regions: [REDACTED]

Visit Type M.
Unit Number PDB07125
Customer Order No. H091
Site Address

CALLBACK/REPAIR No. [REDACTED]
Misuse (Y/N) ☐ Completed (Y/N) ☐
Accidental Damage (Y/N) ☐ Shutdown (Y/N) ☐

GRENFELL TOWER

Unit Type/Customer Unit Reference H091

Customer Name R/L TMO

Maintenance Activity Report (✓ as applicable)

	Checked		Serviceable	
	Y	Not Fitted	Y	N
Car Operating Panel/s	✓		✓	
Car Lighting	✓		✓	
Emergency Alarm Systems	✓		✓	
Hall Buttons / Indicators	✓		✓	
Floor Levels	✓		✓	
Controller / Drive	✓		✓	
Brake	✓		✓	
Machine / Hydro Power Unit	✓		✓	
Overspeed Devices	✓		✓	
Operation of Car Doors	✓		✓	
Car Top	✓		✓	

	Checked		Serviceable	
	Y	Not Fitted	Y	N
Landing Doors	✓		✓	
Counterweight / RAM	✓		✓	
Main Suspension Check	✓		✓	
Pit Area	✓		✓	
Annual / 4 Year Checks				
Door Check				
Suspension Check				
RA Review				
Elec & Mech Check				
Earth Continuity Test				
Brake Check				

Scope of Work & Materials Used (quoting part number where possible)

<u>LIFT SHAFT CLEARDOWN DONE BY Unique</u>

Observations

<u>Various HAWKER Rollers + pick up rollers</u>
<u>require changing - also car door skate</u>
<u>requires new one. - Unique due to come back</u>
<u>on 6th March to do another cleardown.</u>

	Engineer's Name (Please print clearly)	Employee Number	Arrival Time	Depart Time	Total Site Hours	Travel Hours
Engineer 1	<u>D SNALEY</u>	<u>55029</u>	:	:	:	:
Engineer 2	<u>J HALE</u>		:	:	:	:

Date: <u>FEB 14/17</u>	Customer's Name:	Customer's Signature:
------------------------	------------------	-----------------------

Top Copy: Customer Second Copy: Office

MET00036599/1
MET00036599_0001

789.49.477(03.14)