

EXPRESS

Lifts Alliance
Group

Service Visit Report

ISO 9001
BUREAU VERITAS
Certification



Registered in London No. 117366 and Jersey No. 0808373
Registered Office, Chiswick Park Building 5, Ground Floor, 56A Chiswick High Road, W4 5YF

Service and breakdown
London & South East: [REDACTED]
All Other UK Regions: [REDACTED]

Visit Type

M

Unit Number

PD 807174

Customer Order No.

H090

Site Address

GRENfell TOWER

CALLBACK/REPAIR No.

Misuse

(Y/N)

Completed (Y/N)

Accidental Damage (Y/N)

Shutdown (Y/N)

Unit Type/Customer Unit Reference

H090

Customer Name

K/C TMO

Maintenance Activity Report (✓ as applicable)

	Checked		Serviceable	
	Y	Not Fitted	Y	N
Car Operating Panel/s	✓		✓	
Car Lighting	✓		✓	
Emergency Alarm Systems	✓		✓	
Hall Buttons / Indicators	✓		✓	
Floor Levels	✓		✓	
Controller / Drive	✓		✓	
Brake	✓		✓	
Machine / Hydro Power Unit	✓		✓	
Overspeed Devices	✓		✓	
Operation of Car Doors	✓		✓	
Car Top	✓		✓	

	Checked		Serviceable	
	Y	Not Fitted	Y	N
Landing Doors	✓		✓	
Counterweight / RAM	✓		✓	
Main Suspension Check	✓		✓	
Pit Area	✓		✓	
Annual / 4 Year Checks				
Door Check				
Suspension Check				
RA Review				
Elec & Mech Check				
Earth Continuity Test				
Brake Check				

Scope of Work & Materials Used (quoting part number where possible)

Observations

LANDING DOOR Pick up rollers & HANGER
ROLLERS REQUIRE replacement
PIT AREA & SHAFT REQUIRE CLEANDOWN

	Engineer's Name (Please print clearly)	Employee Number	Arrival Time	Depart Time	Total Site Hours	Travel Hours
Engineer 1	D. SNAPEY	57029	:	:	:	:
Engineer 2	L. HARRISON		:	:	:	:

Date: NOV 15 11

Customer's Name:

Customer's Signature:

Top Copy: Customer: Second Copy: Office

MET00042138/1
MET00042138_0001