

Job Number	PD807174
Unit Number	PD807174
Site Address	Grenfell Tower Grenfell Road London W11 1TG
Unit Reference	H090
Date of Service Visit Report	19/12/2016
Visit Type	M2

Customer Order Number	
Parts Used	

Works Completed	
<p>As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :</p> <p>Car Enclosure and COP Emergency Alarm System Indicators and Call Buttons Floor Levels and Selector Machine and Brake Operation of Car Doors Car Top Shaft Equipment</p>	
Signature Declined	N
Decline Reason	

Observations
<p>full shaft cleandown required once builders have completed works. seals leaking slightly on gear. door operator needs setting up once builders have completed works. there is an earth on the ground floor display which is blowing fuses in the psu2unit. contractors have glued display plate to wall and will create damage to wall. customer action required new car door hanger rollers have been fitted. recommend lg1 car lighting and car fan have a separate feed lg1 done nov visit</p>

Total Time on Site	1.45
Total Travel to Site	0.15
Customer Name	Customer Unavailable For Signature
Signed Date & Time	

Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
D Smalley (55029)	19/12/16	12:15	14:00	1.45	0.15	N/A