

EXPRESS

Lifts Alliance
Group

Service Visit Report

ISO 9001

BUREAU VERITAS
Certification



Registered in London No. 147366 and Jersey No. 0098376
Registered Office: Chiswick Park Building 5, Ground Floor, 366 Chiswick High Road, W4 5YF

Service and breakdown
London & South East: [REDACTED]
All Other UK Regions: [REDACTED]

Visit Type

M.

CALLBACK/REPAIR No.

Unit Number

TD 807 775

Misuse

(Y/N)

Completed

(Y/N)

Customer Order No.

H091

Accidental Damage

(Y/N)

Shutdown

(Y/N)

Site Address

GRENfell TOWER.

Unit Type/Customer Unit Reference

H091

Customer Name

K/C TMO.

Maintenance Activity Report (✓ as applicable)

	Checked		Serviceable	
	Y	Not Fitted	Y	N
Car Operating Panel/s	✓		✓	
Car Lighting	✓		✓	
Emergency Alarm Systems	✓		✓	
Hall Buttons / Indicators	✓		✓	
Floor Levels	✓		✓	
Controller / Drive	✓		✓	
Brake	✓		✓	
Machine / Hydro Power Unit	✓		✓	
Overspeed Devices	✓		✓	
Operation of Car Doors	✓		✓	
Car Top	✓		✓	

	Checked		Serviceable	
	Y	Not Fitted	Y	N
Landing Doors	✓		✓	
Counterweight / RAM	✓		✓	
Main Suspension Check	✓		✓	
Pit Area	✓		✓	
Annual / 4 Year Checks				
Door Check				
Suspension Check				
RA Review				
Elec & Mech Check				
Earth Continuity Test				
Brake Check				

Scope of Work & Materials Used (quoting part number where possible)

Observations

LANDING DOOR Pickups rollers require renewal
Also HANGER ROLLERS
LIFT SHAFT REQUIRES CLEAN DOWN

	Engineer's Name (Please print clearly)	Employee Number	Arrival Time	Depart Time	Total Site Hours	Travel Hours
Engineer 1	D. SANCHEZ	55029	:	:	:	:
Engineer 2	R. HARMAN		:	:	:	:

Date:

Nov

Customer's Name:

Customer's Signature:

Top Copy: Customer Second Copy: Office

MET00042141/1
MET00042141_0001