

Repair Visit Report



Job Number	CA2SL5
Unit Number	PD807175
Site Address	Grenfell Tower Grenfell Road London W11 1TG
Unit Reference	H091
Date of Service Visit Report	26/03/2014
Job Completed	Y
Misuse/Acc Damage	

Customer Order Number	201358275
Parts Used	

Works Completed	<p>Attended site and found the unit running on arrival . The equipment was checked over with no fault found and the unit returned to normal service.</p>
-----------------	--

Observations	
--------------	--

Declined	N
Decline Reason	
Total Time on Site	1.00
Total Travel to Site	0.30

Customer Name	Customer Unavailable For Signature
Signed Date & Time	

Attending Engineer(s)							Customer Signoffs
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site		
D Linney (58510)	26/03/14	13:30	14:30	1.00	0.30		N/A

Repair Visit Report



Job Number CA2UG8

Unit Number PD807175

Site Address
Grenfell Tower
Grenfell Road
London W11 1TG

Unit Reference H091

Date of Service Visit Report 26/03/2014

Job Completed N Misuse/Acc Damage

Works Completed

Attended site and found an issue with a control panel phase failure reversal. The unit has been left isolated awaiting materials. Additional Comments by Engineer: found w.o a ran and tested, intermittently loosing lar traced to 11 and 14 on pfrr, pfrr faulty and carel temp unit u,s lsd parts req. will report lsd

Customer Order Number 1965045

Parts Used

Observations

Declined N

Decline Reason

Total Time on Site 1.47

Total Travel to Site 0.00

Customer Name

Signed Date & Time

**Customer
Unavailable
For Signature**

Attending Engineer(s)

Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
S Talidi (58448)	26/03/14	20:08	21:01	0.53	0.00	N/A
J Myrmus (60034)	26/03/14	20:09	21:03	0.54	0.00	N/A

Repair Visit Report



Job Number	CA3GQ4			Customer Order Number			
Unit Number	PD807175			Parts Used			
Site Address	Grenfell Tower Grenfell Road London W11 1TG						
Unit Reference	H091						
Date of Service Visit Report	02/04/2014						
Job Completed	Y	Misuse/Acc Damage					
Works Completed	<p>Attended site and found the unit running on arrival . The equipment was checked over with no fault found and the unit returned to normal service.</p>			Observations			
Declined	N			Customer Name	Customer Unavailable For Signature		
Decline Reason							
Total Time on Site	0.35						
Total Travel to Site	0.55						
Signed Date & Time							
Attending Engineer(s)							
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs	
R Roberts (57189)	01/04/14	08:55	09:30	0.35	0.55	N/A	

Repair Visit Report



Job Number	CA5WJ9		Customer Order Number	1974300		
Unit Number	PD807175		Parts Used			
Site Address	Grenfell Tower Grenfell Road London W11 1TG					
Unit Reference	H091					
Date of Service Visit Report	27/04/2014					
Job Completed	Y	Misuse/Acc Damage	Observations			
Works Completed						
<p>Attended site and found the unit running on arrival . The equipment was checked over with no fault found and the unit returned to normal service. Additional Comments by Engineer: fire alarm test</p>						
Declined	N		Customer Name Signed Date & Time Customer Unavailable For Signature			
Decline Reason						
Total Time on Site	0.01					
Total Travel to Site	0.01					
Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
D Blackwell (58517)	26/04/14	21:36	21:37	0.01	0.01	N/A

Repair Visit Report



Job Number CA9TW0

Unit Number PD807175

Site Address
Grenfell Tower
Grenfell Road
London W11 1TG

Unit Reference H091

Date of Service Visit Report 04/06/2014

Job Completed Y Misuse/Acc Damage

Works Completed

Attended site and found an issue with a landing door/gate equipment. The equipment was adjusted and the unit returned to normal service

Customer Order Number 1986041

Parts Used

Observations

Declined N

Decline Reason

Total Time on Site 0.21

Total Travel to Site 0.00

Customer Name

Signed Date & Time

**Customer
Unavailable
For Signature**

Attending Engineer(s)

Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
S Haggarty (58388)	04/06/14	21:39	22:00	0.21	0.00	N/A

Repair Visit Report



Job Number	CA9RZ6			Customer Order Number	201410380		
Unit Number	PD807175			Parts Used			
Site Address	Grenfell Tower Grenfell Road London W11 1TG						
Unit Reference	H091						
Date of Service Visit Report	04/06/2014						
Job Completed	Y	Misuse/Acc Damage		Observations			
Works Completed							
Attended site and found an issue with a landing door/gate equipment. A repair was completed to resolve the issue and the unit returned to normal service							
Declined	N			Customer Name		Customer Unavailable For Signature	
Decline Reason							
Total Time on Site	1.35			Signed Date & Time			
Total Travel to Site	0.20						
Attending Engineer(s)							
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs	
D Linney (58510)	04/06/14	14:50	16:25	1.35	0.20	N/A	

Repair Visit Report



Job Number	CB1FG7			Customer Order Number	1990534		
Unit Number	PD807175			Parts Used			
Site Address	Grenfell Tower Grenfell Road London W11 1TG						
Unit Reference	H091						
Date of Service Visit Report	18/06/2014			Observations			
Job Completed	Y	Misuse/Acc Damage					
Works Completed	<p>Attended site and found the unit running on arrival . The equipment was checked over with no fault found and the unit returned to normal service.</p>						
Declined	N			Customer Name	Customer Unavailable For Signature		
Decline Reason							
Total Time on Site	1.26						
Total Travel to Site	0.00			Signed Date & Time			
Attending Engineer(s)							
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs	
M Dawkins (58444)	18/06/14	17:54	19:20	1.26	0.00	N/A	

Repair Visit Report



Job Number	CB7CU5			Customer Order Number	2007117		
Unit Number	PD807175			Parts Used			
Site Address	Grenfell Tower Grenfell Road London W11 1TG						
Unit Reference	H091						
Date of Service Visit Report	10/08/2014						
Job Completed	Y	Misuse/Acc Damage		Observations			
Works Completed	<p>Attended site and found an issue with a control panel fuse. A part was replaced to resolve the issue and the unit returned to normal service</p>						
Declined	N						
Decline Reason							
Total Time on Site	0.30			Customer Name	Customer Unavailable For Signature		
Total Travel to Site	0.00			Signed Date & Time			
Attending Engineer(s)							
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs	
D Thomas (58487)	10/08/14	15:30	16:00	0.30	0.00	N/A	

Repair Visit Report



Job Number	CB7EE7			Customer Order Number	201420910																
Unit Number	PD807175			Parts Used																	
Site Address	Grenfell Tower Grenfell Road London W11 1TG																				
Unit Reference	H091																				
Date of Service Visit Report	11/08/2014			Observations																	
Job Completed	Y	Misuse/Acc Damage	Y																		
Works Completed	<p>Attended site and found an issue with a landing call push. A repair was completed to resolve the issue and the unit returned to normal service. Additional Comments by Engineer: found trapped wire on push on w floor</p>																				
Declined	N			Customer Name	Customer Unavailable For Signature																
Decline Reason																					
Total Time on Site	1.00																				
Total Travel to Site	0.00			Signed Date & Time																	
Attending Engineer(s) <table border="1"> <thead> <tr> <th>Engineer Name</th> <th>Date Attended</th> <th>Site Arrival</th> <th>Site Depart</th> <th>Time on site</th> <th>Travel to site</th> <th>Customer Signoffs</th> </tr> </thead> <tbody> <tr> <td>D Linney (58510)</td> <td>11/08/14</td> <td>12:00</td> <td>13:00</td> <td>1.00</td> <td>0.00</td> <td>N/A</td> </tr> </tbody> </table>								Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs	D Linney (58510)	11/08/14	12:00	13:00	1.00	0.00	N/A
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs															
D Linney (58510)	11/08/14	12:00	13:00	1.00	0.00	N/A															

Repair Visit Report



Job Number	CC1EV9		Customer Order Number	201427100		
Unit Number	PD807175		Parts Used			
Site Address	Grenfell Tower Grenfell Road London W11 1TG					
Unit Reference	H091					
Date of Service Visit Report	18/09/2014					
Job Completed	Y	Misuse/Acc Damage				
Works Completed			Observations			
<p>Attended site and found the unit running on arrival . The equipment was checked over with no fault found and the unit returned to normal service.</p>						
Declined	N		Customer Name			
Decline Reason			<p>Customer Unavailable For Signature</p>			
Total Time on Site	2.20					
Total Travel to Site	0.00					
			Signed Date & Time			
Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
T Williams (58512)	17/09/14	12:30	14:00	1.30	0.00	N/A
J Petty (58459)	17/09/14	20:10	21:00	0.50	0.00	N/A

Repair Visit Report



Job Number	CC2BS8			Customer Order Number	201428517		
Unit Number	PD807175			Parts Used			
Site Address	Grenfell Tower Grenfell Road London W11 1TG						
Unit Reference	H091						
Date of Service Visit Report	24/09/2014			Observations			
Job Completed	N	Misuse/Acc Damage					
Works Completed	<p>Attended site and found the unit running on arrival . The equipment was checked over with no fault found and the unit returned to normal service.</p>						
Declined	N			Customer Name	Customer Unavailable For Signature		
Decline Reason							
Total Time on Site	1.32						
Total Travel to Site	0.00			Signed Date & Time			
Attending Engineer(s)							
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs	
J Sutton (54047)	24/09/14	18:30	19:16	0.46	0.00		N/A
K Edgar (56109)	24/09/14	18:30	19:16	0.46	0.00		N/A

Repair Visit Report



Job Number	CC3AC3			Customer Order Number		
Unit Number	PD807175			Parts Used		
Site Address	Grenfell Tower Grenfell Road London W11 1TG					
Unit Reference	H091					
Date of Service Visit Report	03/10/2014					
Job Completed	Y	Misuse/Acc Damage				
Works Completed	<p>Attended site and found an issue with a car door/gate equipment. The equipment was adjusted and the unit returned to normal service. Additional Comments by Engineer: made adjustment to skate. gal door arm bearing has worn a hole in arm causing extra movement. new door arm required</p>			Observations		
Declined	N			Customer Name	Customer Unavailable For Signature	
Decline Reason						
Total Time on Site	1.55			Signed Date & Time		
Total Travel to Site	0.00					
Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
S Haggarty (58388)	03/10/14	12:41	14:36	1.55	0.00	N/A

Repair Visit Report



Job Number CC3FK1

Unit Number PD807175

Site Address
Grenfell Tower
Grenfell Road
London W11 1TG

Unit Reference H091

Date of Service Visit Report 05/10/2014

Job Completed Y Misuse/Acc Damage

Works Completed

Attended site and found an issue with a car door/gate equipment. The unit has been left isolated awaiting materials. Additional Comments by Engineer: lift shutdown, due to gal door arm bearing missing will cause trapping, needs renewing

Customer Order Number

Parts Used

Observations

Declined N

Decline Reason

Total Time on Site 0.27

Total Travel to Site 0.00

Customer Name

Signed Date & Time

**Customer
Unavailable
For Signature**

Attending Engineer(s)

Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
T Parker (58461)	05/10/14	15:04	15:31	0.27	0.00	N/A

Repair Visit Report



Job Number		CC3FK1		Customer Order Number			
Unit Number		PD807175		Parts Used			
Site Address		Grenfell Tower Grenfell Road London W11 1TG					
Unit Reference		H091					
Date of Service Visit Report		07/10/2014					
Job Completed		Y		Misuse/Acc Damage			
Works Completed				Observations			
Attended site and found an issue with a car door/gate equipment. A part was replaced to resolve the issue and the unit returned to normal service. Additional Comments by Engineer: fitted new car door drive arm and set up doors							
Declined		N		Customer Name		Customer Unavailable For Signature	
Decline Reason				Signed Date & Time			
Total Time on Site		2.00					
Total Travel to Site		1.00					
Attending Engineer(s)							
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs	
D Linney (58510)	07/10/14	10:00	12:00	2.00	1.00	N/A	

Repair Visit Report



Job Number	CC7TW6			Customer Order Number	201437954		
Unit Number	PD807175			Parts Used			
Site Address	Grenfell Tower Grenfell Road London W11 1TG						
Unit Reference	H091						
Date of Service Visit Report	15/11/2014						
Job Completed	N	Misuse/Acc Damage		Observations			
Works Completed							
Attended site and found an issue with a car frame guide rollers. The unit has been left isolated awaiting materials.							
Declined	N			Customer Name			
Decline Reason				Customer Unavailable For Signature			
Total Time on Site	1.30						
Total Travel to Site	0.30						
Attending Engineer(s)				Signed Date & Time			
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs	
D Thomas (58487)	14/11/14	10:30	12:00	1.30	0.30	N/A	

Repair Visit Report



Job Number	CC8GX6	Customer Order Number	201438727			
Unit Number	PD807175	Parts Used				
Site Address	Grenfell Tower Grenfell Road London W11 1TG					
Unit Reference	H091	Observations				
Date of Service Visit Report	19/11/2014					
Job Completed	Y	Misuse/Acc Damage				
Works Completed	<p>Attended site and found the unit running on arrival . The equipment was checked over with no fault found and the unit returned to normal service.</p>					
Declined	N	Customer Name	Customer Unavailable For Signature			
Decline Reason		Signed Date & Time				
Total Time on Site	2.49					
Total Travel to Site	0.05					
Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
S Haggarty (58388)	19/11/14	12:57	15:46	2.49	0.05	N/A

Repair Visit Report



Job Number CC9JU2		Customer Order Number 201440926				
Unit Number PD807175		Parts Used				
Site Address Grenfell Tower Grenfell Road London W11 1TG						
Unit Reference H091						
Date of Service Visit Report 28/11/2014						
Job Completed Y	Misuse/Acc Damage Y	Observations				
Works Completed Attended site and found an issue with the unit on site . The equipment was reset and the unit returned to normal service. Additional Comments by Engineer: arrived at site lift w.o.a lift was out of service due to builders on site						
Declined N						
Decline Reason						
Total Time on Site 1.00						
Total Travel to Site 0.00		Customer Name				
		Signed Date & Time				
		Customer Unavailable For Signature				
Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
T Williams (58512)	28/11/14	16:00	17:00	1.00	0.00	N/A