

IN A MATTER CONCERNING THE GRENFELL TOWER INQUIRY

EXHIBIT MW/3

Repair Visit Report



Job Number	CP1JW6	Customer Order Number	201709213			
Unit Number	PD807174	Parts Used				
Site Address	Grenfell Tower Grenfell Road London W11 1TG					
Unit Reference	H090	Observations				
Date of Service Visit Report	05/06/2017					
Job Completed	Y	Misuse/Acc Damage				
Works Completed	<p>Attended site and found an issue with a car door/gate operator. The equipment was adjusted and the unit returned to normal service. Additional Comments by Engineer: door limit cam adjusted to suit</p>					
Declined	N	Customer Name	Customer Unavailable For Signature			
Decline Reason						
Total Time on Site	1.30	Signed Date & Time				
Total Travel to Site	0.00					
Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
A Smart (58579)	05/06/17	15:30	17:00	1.30	0.00	N/A

Repair Visit Report



Job Number CP1QD1

Unit Number PD807174

Site Address
Grenfell Tower
Grenfell Road
London W11 1TG

Unit Reference H090

Date of Service Visit Report 07/06/2017

Job Completed Y Misuse/Acc Damage

Works Completed

Attended site and found an issue with a landing door/gate lock. The equipment was adjusted and the unit returned to normal service. Additional Comments by Engineer: adjusted 1st floor smoke baffle, stopping doors closing

Customer Order Number 201709655

Parts Used

Observations

Declined N

Decline Reason

Total Time on Site 1.00

Total Travel to Site 0.00

Customer Name

Signed Date & Time

**Customer
Unavailable
For Signature**

Attending Engineer(s)

Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
A Smart (58579)	07/06/17	09:30	10:30	1.00	0.00	N/A