

**IN A MATTER CONCERNING THE GRENFELL TOWER INQUIRY**

---

**EXHIBIT MFT/6**

---



# ENGINEER SERVICE REPORT

Form No. 140/11 05/10

245365

**EXPRESS**

Lifts Alliance Group

*Lifts for London*

DATE 26/2/14.

ENGINEER D LINNEY

SITE ADDRESS GENEVEH TOWN

CONTRACT No. PD807176

TYPE OF MACHINE TRACTION

No. OF MACHINE H090

PART	S	WBS	SBOH	SBR	PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY	/				18 BALANCE WEIGHT SHOES	/			
2 LANDING GATES OR DOORS	/				19 CAR LANDING DOOR ACCESSORIES	/			
3 CAR GATE(S) OR DOORS	/				20 DOOR GEAR	/			
4 LANDING GATE OR DOOR LOCKS	/				21 PUSHES & INDICATORS	/			
5 CAR GATE(S) OR DOOR LOCKS	/				22 WORM & SPUR GEARING	/			
6 OTHER GATE OR DOOR FASTENINGS	/				23 HOISTING MOTOR	/			
7 CAR OR PLATFORM FITTINGS	/				24 GENERATOR	/			
8 CAR GUIDES AND FITTINGS	/				25 CONTROLLER CONTACTS	/			
9 BUFFERS	/				26 WIRING	/			
10 OVER - RUNNING DEVICES	/				27 BRAKE & BRAKE LININGS	/			
11 SUSPENSION RODS	/				28 SELECTOR CONTACTS	/			
12 GOVERNOR ROPES	/				29 PULLEY WHEELS	/			
13 SAFETY ROPES	/				30 LIFT SHAFT SWITCHES	/			
14 SAFETY ROPES OR TAPES	/				31 RAM & CYLINDER	/			
15 SAFETY GEAR	/				32 VALVE GEAR	/			
16 OVERSPEED GOVERNOR CAR	/				33 RAM PACKINGS	/			
17 CAR SHOES OR ROLLERS	/				34 WHAT PARTS (IF ANY) INACCESSIBLE	/			

S = SATISFACTORY    WBS = WORN BUT SERVICEABLE    SBOH = SHOULD BE OVERHAULED    SBR = SHOULD BE RENEWED

TIME OF ARRIVAL \_\_\_\_\_ TIME OF DEPARTURE \_\_\_\_\_

MATERIALS

*ROUTINE VISIT*

OFFICE USE ONLY

ENGINEER'S REPORT / REMARKS / JHA

CUSTOMER'S SIGNATURE \_\_\_\_\_ ENGINEER'S SIGNATURE \_\_\_\_\_

Express House, 100 Rolt Street, Deptford, London SE8 5NN  
Tel: \_\_\_\_\_ Fax: \_\_\_\_\_



CL80244



Lifts for London

# ENGINEER SERVICE REPORT

Form No. 140/11 05/10

230336

THE  
**EXPRESS**  
LIFTS ALLIANCE

DATE 26 3 14

ENGINEER E J DEACON

SITE ADDRESS GREENEFULL

CONTRACT No. PP807174

TYPE OF MACHINE PAS-TH4c

No. OF MACHINE H174

PART	S	WBS	SBON	SBR	PART	S	WBS	SBON	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY	/	/	/	/	18 BALANCE WEIGHT SHOES	/	/	/	/
2 LANDING GATES OR DOORS	/	/	/	/	19 CAR LANDING DOOR ACCESSORIES	/	/	/	/
3 CAR GATE(S) OR DOORS	/	/	/	/	20 DOOR GEAR	/	/	/	/
4 LANDING GATE OR DOOR LOCKS	/	/	/	/	21 PUSHES & INDICATORS	/	/	/	/
5 CAR GATE(S) OR DOOR LOCKS	/	/	/	/	22 WORM & SPUR GEARING	/	/	/	/
6 OTHER GATE OR DOOR FASTENINGS	/	/	/	/	23 HOISTING MOTOR	/	/	/	/
7 CAR OR PLATFORM FITTINGS	/	/	/	/	24 GENERATOR	/	/	/	/
8 CAR GUIDES AND FITTINGS	/	/	/	/	25 CONTROLLER CONTACTS	/	/	/	/
9 BUFFERS	/	/	/	/	26 WIRING	/	/	/	/
10 OVER - RUNNING DEVICES	/	/	/	/	27 BRAKE & BRAKE LININGS	/	/	/	/
11 SUSPENSION RODS	/	/	/	/	28 SELECTOR CONTACTS	/	/	/	/
12 GOVERNOR ROPES	/	/	/	/	29 PULLEY WHEELS	/	/	/	/
13 SAFETY ROPES	/	/	/	/	30 LIFT SHAFT SWITCHES	/	/	/	/
14 SAFETY ROPES OR TAPES	/	/	/	/	31 RAM & CYLINDER	/	/	/	/
15 SAFETY GEAR	/	/	/	/	32 VALVE GEAR	/	/	/	/
16 OVERSPEED GOVERNOR CAR	/	/	/	/	33 RAM PACKINGS	/	/	/	/
17 CAR SHOES OR ROLLERS	/	/	/	/	34 WHAT PARTS (IF ANY) INACCESSIBLE	/	/	/	/

S = SATISFACTORY

WBS = WORN BUT SERVICEABLE

SBON = SHOULD BE OVERHAULED

SBR = SHOULD BE RENEWED

TIME OF ARRIVAL \_\_\_\_\_

TIME OF DEPARTURE \_\_\_\_\_

OFFICE USE ONLY

MATERIALS

ENGINEER'S REPORT / REMARKS / JHA

CUSTOMER'S SIGNATURE \_\_\_\_\_

ENGINEER'S SIGNATURE E J Deacon

PDERS Unit 6, Bermondsey Trading Estate Rotherhithe New Road London SE16 3LL  
Tel: \_\_\_\_\_ Fax: \_\_\_\_\_

ISO 9001  
BUREAU VERITAS  
Certification



CL02244





Lifts for London

## ENGINEER SERVICE REPORT

244269

**EXPRESS**  
 Lifts Alliance  
 Group
DATE 26-04-14ENGINEER J. H. A. K. E.SITE ADDRESS GRENFELL TOWERCONTRACT No. PD. 837174TYPE OF MACHINE PAS-TRACNo. OF MACHINE 11090

PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY		/		
2 LANDING GATES OR DOORS		/		
3 CAR GATE(S) OR DOORS		/		
4 LANDING GATE OR DOOR LOCKS		/		
5 CAR GATE(S) OR DOOR LOCKS		/		
6 OTHER GATE OR DOOR FASTENINGS		/		
7 CAR OR PLATFORM FITTINGS		/		
8 CAR GUIDES AND FITTINGS		/		
9 BUFFERS		/		
10 OVER - RUNNING DEVICES		/		
11 SUSPENSION RODS		/		
12 GOVERNOR ROPES		/		
13 SAFETY ROPES		/		
14 SAFETY ROPES OR TAPES		/		
15 SAFETY GEAR		/		
16 OVERSPEED GOVERNOR CAR		/		
17 CAR SHOES OR ROLLERS		/		

PART	S	WBS	SBOH	SBR
18 BALANCE WEIGHT SHOES		/		
19 CAR LANDING DOOR ACCESSORIES		/		
20 DOOR GEAR		/		
21 PUSHES & INDICATORS		/		
22 WORM & SPUR GEARING		/		
23 HOISTING MOTOR		/		
24 GENERATOR		/		
25 CONTROLLER CONTACTS		/		
26 WIRING		/		
27 BRAKE & BRAKE LININGS		/		
28 SELECTOR CONTACTS		/		
29 PULLEY WHEELS		/		
30 LIFT SHAFT SWITCHES		/		
31 RAM & CYLINDER		/		
32 VALVE GEAR		/		
33 RAM PACKINGS		/		
34 WHAT PARTS (IF ANY) INACCESSIBLE		/		

S = SATISFACTORY

WBS = WORN BUT SERVICEABLE

SBOH = SHOULD BE OVERHAULED

SBR = SHOULD BE RENEWED

TIME OF ARRIVAL \_\_\_\_\_

TIME OF DEPARTURE \_\_\_\_\_

OFFICE USE ONLY

MATERIALS

ENGINEER'S REPORT / REMARKS / JHA

CUSTOMER'S SIGNATURE \_\_\_\_\_

ENGINEER'S SIGNATURE [Signature]Express House, 100 Rolt Street, Deptford, London SE8 5NN  
Tel: \_\_\_\_\_ Fax: \_\_\_\_\_ISO 9001  
BUREAU VERITAS  
Certification

CL90244





# ENGINEER SERVICE REPORT

Form No. 140/11 05/10

245161

**EXPRESS**

Lifts Alliance Group

*Lifts for London*

DATE

29/5/14

ENGINEER

D. LINNLEY

SITE ADDRESS

GREENFELL TOWER

CONTRACT No.

PD807174

TYPE OF MACHINE

TRACON

No. OF MACHINE

H090

PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2 LANDING GATES OR DOORS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3 CAR GATE(S) OR DOORS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4 LANDING GATE OR DOOR LOCKS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5 CAR GATE(S) OR DOOR LOCKS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6 OTHER GATE OR DOOR FASTENINGS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7 CAR OR PLATFORM FITTINGS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8 CAR GUIDES AND FITTINGS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9 BUFFERS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10 OVER - RUNNING DEVICES	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11 SUSPENSION RODS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12 GOVERNOR ROPES	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13 SAFETY ROPES	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14 SAFETY ROPES OR TAPES	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15 SAFETY GEAR	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16 OVERSPEED GOVERNOR CAR	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17 CAR SHOES OR ROLLERS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

S = SATISFACTORY

WBS = WORN BUT SERVICEABLE

SBOH = SHOULD BE OVERHAULED

SBR = SHOULD BE RENEWED

PART	S	WBS	SBOH	SBR
18 BALANCE WEIGHT SHOES	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
19 CAR LANDING DOOR ACCESSORIES	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
20 DOOR GEAR	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
21 PUSHES & INDICATORS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
22 WORM & SPUR GEARING	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
23 HOISTING MOTOR	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
24 GENERATOR	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
25 CONTROLLER CONTACTS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
26 WIRING	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
27 BRAKE & BRAKE LININGS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
28 SELECTOR CONTACTS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
29 PULLEY WHEELS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
30 LIFT SHAFT SWITCHES	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
31 RAM & CYLINDER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
32 VALVE GEAR	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
33 RAM PACKINGS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
34 WHAT PARTS (IF ANY) INACCESSIBLE	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

TIME OF ARRIVAL

TIME OF DEPARTURE

OFFICE USE ONLY

MATERIALS

*ROUTINE VISIT*

ENGINEER'S REPORT / REMARKS / JHA

CUSTOMER'S SIGNATURE

ENGINEER'S SIGNATURE

Express House, 100 Rolt Street, Deptford, London SE8 5NN

Tel:

Fax:

ISO 9001  
BUREAU VERITAS  
Certification



CLB0244

PDR00000047/5

PDR00000047 0005



# ENGINEER SERVICE REPORT

Form No. 140/11 05/10

245197

**EXPRESS**  
Lifts Alliance  
Group

*Lifts for London*

DATE

*25/6/14*

ENGINEER

*D. Linn*

SITE ADDRESS

*Greenfell tower*

CONTRACT No.

*P0807174*

TYPE OF MACHINE

*TRACTION*

No. OF MACHINE

*12090*

PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY		/		
2 LANDING GATES OR DOORS		/		
3 CAR GATE(S) OR DOORS		/		
4 LANDING GATE OR DOOR LOCKS		/		
5 CAR GATE(S) OR DOOR LOCKS		/		
6 OTHER GATE OR DOOR FASTENINGS		/		
7 CAR OR PLATFORM FITTINGS		/		
8 CAR GUIDES AND FITTINGS		/		
9 BUFFERS		/		
10 OVER - RUNNING DEVICES		/		
11 SUSPENSION RODS		/		
12 GOVERNOR ROPES		/		
13 SAFETY ROPES		/		
14 SAFETY ROPES OR TAPES		/		
15 SAFETY GEAR		/		
16 OVERSPEED GOVERNOR CAR		/		
17 CAR SHOES OR ROLLERS		/		

S = SATISFACTORY

WBS = WORN BUT SERVICEABLE

SBOH = SHOULD BE OVERHAULED

SBR = SHOULD BE RENEWED

PART	S	WBS	SBOH	SBR
18 BALANCE WEIGHT SHOES		/		
19 CAR LANDING DOOR ACCESSORIES		/		
20 DOOR GEAR		/		
21 PUSHES & INDICATORS		/		
22 WORM & SPUR GEARING		/		
23 HOISTING MOTOR		/		
24 GENERATOR		/		
25 CONTROLLER CONTACTS		/		
26 WIRING		/		
27 BRAKE & BRAKE LININGS		/		
28 SELECTOR CONTACTS		/		
29 PULLEY WHEELS		/		
30 LIFT SHAFT SWITCHES		/		
31 RAM & CYLINDER		/		
32 VALVE GEAR		/		
33 RAM PACKINGS		/		
34 WHAT PARTS (IF ANY) INACCESSIBLE		/		

TIME OF ARRIVAL

TIME OF DEPARTURE

OFFICE USE ONLY

MATERIALS

*ROUTINE - VISIT*

ENGINEER'S REPORT / REMARKS / JHA

CUSTOMER'S SIGNATURE

ENGINEER'S SIGNATURE

Express House, 100 Rolt Street, Deptford, London SE8 5NN

Tel: [REDACTED] Fax: [REDACTED]

ISO 9001  
BUREAU VERITAS  
Certification



CL80244





# ENGINEER SERVICE REPORT

Form No. 140/11 05/10

247944

**EXPRESS**  
Lifts Alliance  
Group

*Lifts for London*

DATE 28/7/14

ENGINEER D. LINNBY

SITE ADDRESS GREENFELT TOWER

CONTRACT No. P0807174

TYPE OF MACHINE TRACTION

No. OF MACHINE H090

PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY		/		
2 LANDING GATES OR DOORS		/		
3 CAR GATE(S) OR DOORS		/		
4 LANDING GATE OR DOOR LOCKS		/		
5 CAR GATE(S) OR DOOR LOCKS		/		
6 OTHER GATE OR DOOR FASTENINGS		/		
7 CAR OR PLATFORM FITTINGS		/		
8 CAR GUIDES AND FITTINGS		/		
9 BUFFERS		/		
10 OVER - RUNNING DEVICES		/		
11 SUSPENSION RODS		/		
12 GOVERNOR ROPES		/		
13 SAFETY ROPES		/		
14 SAFETY ROPES OR TAPES		/		
15 SAFETY GEAR		/		
16 OVERSPEED GOVERNOR CAR		/		
17 CAR SHOES OR ROLLERS		/		

PART	S	WBS	SBOH	SBR
18 BALANCE WEIGHT SHOES		/		
19 CAR LANDING DOOR ACCESSORIES		/		
20 DOOR GEAR		/		
21 PUSHES & INDICATORS		/		
22 WORM & SPUR GEARING		/		
23 HOISTING MOTOR		/		
24 GENERATOR		/		
25 CONTROLLER CONTACTS		/		
26 WIRING		/		
27 BRAKE & BRAKE LININGS		/		
28 SELECTOR CONTACTS		/		
29 PULLEY WHEELS		/		
30 LIFT SHAFT SWITCHES		/		
31 RAM & CYLINDER		/		
32 VALVE GEAR		/		
33 RAM PACKINGS		/		
34 WHAT PARTS (IF ANY) INACCESSIBLE		/		

S = SATISFACTORY WBS = WORN BUT SERVICEABLE SBOH = SHOULD BE OVERHAULED SBR = SHOULD BE RENEWED

TIME OF ARRIVAL \_\_\_\_\_ TIME OF DEPARTURE \_\_\_\_\_

MATERIALS

*ROUTINE VISIT*

ENGINEER'S REPORT / REMARKS / JHA

CUSTOMER'S SIGNATURE \_\_\_\_\_ ENGINEER'S SIGNATURE \_\_\_\_\_

Express House, 100 Rolt Street, Deptford, London SE8 5NN  
Tel: \_\_\_\_\_ Fax: \_\_\_\_\_



CLB0244





Lifts for London

# ENGINEER SERVICE REPORT

Form No. 140/11 05/10

241679

**EXPRESS**  
Lifts Alliance  
Group

DATE 11/8/14

ENGINEER D. LANNY

SITE ADDRESS GREENFALL TOWER

CONTRACT No. P0807174

TYPE OF MACHINE TRACTION

No. OF MACHINE H090

PART	S	WBS	SBOH	SBR	PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY	/				18 BALANCE WEIGHT SHOES	/			
2 LANDING GATES OR DOORS	/				19 CAR LANDING DOOR ACCESSORIES	/			
3 CAR GATE(S) OR DOORS	/				20 DOOR GEAR	/			
4 LANDING GATE OR DOOR LOCKS	/				21 PUSHES & INDICATORS	/			
5 CAR GATE(S) OR DOOR LOCKS	/				22 WORM & SPUR GEARING	/			
6 OTHER GATE OR DOOR FASTENINGS	/				23 HOISTING MOTOR	/			
7 CAR OR PLATFORM FITTINGS	/				24 GENERATOR	/			
8 CAR GUIDES AND FITTINGS	/				25 CONTROLLER CONTACTS	/			
9 BUFFERS	/				26 WIRING	/			
10 OVER - RUNNING DEVICES	/				27 BRAKE & BRAKE LININGS	/			
11 SUSPENSION RODS	/				28 SELECTOR CONTACTS	/			
12 GOVERNOR ROPES	/				29 PULLEY WHEELS	/			
13 SAFETY ROPES	/				30 LIFT SHAFT SWITCHES	/			
14 SAFETY ROPES OR TAPES	/				31 RAM & CYLINDER	/			
15 SAFETY GEAR	/				32 VALVE GEAR	/			
16 OVERSPEED GOVERNOR CAR	/				33 RAM PACKINGS	/			
17 CAR SHOES OR ROLLERS	/				34 WHAT PARTS (IF ANY) INACCESSIBLE	/			

S = SATISFACTORY      WBS = WORN BUT SERVICEABLE      SBOH = SHOULD BE OVERHAULED      SBR = SHOULD BE RENEWED

TIME OF ARRIVAL \_\_\_\_\_ TIME OF DEPARTURE \_\_\_\_\_

OFFICE USE ONLY

MATERIALS

*ROUTINE VISIT*

ENGINEER'S REPORT / REMARKS / JHA

CUSTOMER'S SIGNATURE \_\_\_\_\_

ENGINEER'S SIGNATURE 

Express House, 100 Rolt Street, Deptford, London SE8 5NN  
Tel: \_\_\_\_\_ Fax: \_\_\_\_\_

ISO 9001  
BUREAU VERITAS  
Certification



CL80244



# ENGINEER SERVICE REPORT

Form No. 140/11 05/10

259740

**EXPRESS**

Lifts Alliance  
Group

Lifts for London

DATE 12/9/14

ENGINEER D Linnby

SITE ADDRESS GREEN RELL Tower

CONTRACT No. PDR07174

TYPE OF MACHINE TRACTION

No. OF MACHINE H090

PART	S	WBS	SBOH	SBR	PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY	/				18 BALANCE WEIGHT SHOES	/			
2 LANDING GATES OR DOORS	/				19 CAR LANDING DOOR ACCESSORIES	/			
3 CAR GATE(S) OR DOORS	/				20 DOOR GEAR	/			
4 LANDING GATE OR DOOR LOCKS	/				21 PUSHES & INDICATORS	/			
5 CAR GATE(S) OR DOOR LOCKS	/				22 WORM & SPUR GEARING	/			
6 OTHER GATE OR DOOR FASTENINGS	/				23 HOISTING MOTOR	/			
7 CAR OR PLATFORM FITTINGS	/				24 GENERATOR	/			
8 CAR GUIDES AND FITTINGS	/				25 CONTROLLER CONTACTS	/			
9 BUFFERS	/				26 WIRING	/			
10 OVER - RUNNING DEVICES	/				27 BRAKE & BRAKE LININGS	/			
11 SUSPENSION RODS	/				28 SELECTOR CONTACTS	/			
12 GOVERNOR ROPES	/				29 PULLEY WHEELS	/			
13 SAFETY ROPES	/				30 LIFT SHAFT SWITCHES	/			
14 SAFETY ROPES OR TAPES	/				31 RAM & CYLINDER	/			
15 SAFETY GEAR	/				32 VALVE GEAR	/			
16 OVERSPEED GOVERNOR CAR	/				33 RAM PACKINGS	/			
17 CAR SHOES OR ROLLERS	/				34 WHAT PARTS (IF ANY) INACCESSIBLE	/			

S = SATISFACTORY

WBS = WORN BUT SERVICEABLE

SBOH = SHOULD BE OVERHAULED

SBR = SHOULD BE RENEWED

TIME OF ARRIVAL \_\_\_\_\_ TIME OF DEPARTURE \_\_\_\_\_

MATERIALS

ROUTINE VISIT

OFFICE USE ONLY

ENGINEER'S REPORT / REMARKS / JHA

CUSTOMER'S SIGNATURE \_\_\_\_\_

ENGINEER'S SIGNATURE \_\_\_\_\_

Express House, 100 Rolt Street, Deptford, London SE8 5NN  
Tel: [REDACTED] Fax: [REDACTED]



CLB0244





# ENGINEER SERVICE REPORT

Form No. 140/11 05/10

**258102**  
**EXPRESS**  
Lifts Alliance  
Group

*Lifts for London*

DATE 7/10/14

ENGINEER D. Linnig

SITE ADDRESS GRENFELL TOWER

CONTRACT No. PD807174

TYPE OF MACHINE TRACTION

No. OF MACHINE H 90

PART	S	WBS	SBOH	SBR	PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY	/				18 BALANCE WEIGHT SHOES	/			
2 LANDING GATES OR DOORS	/				19 CAR LANDING DOOR ACCESSORIES	/			
3 CAR GATE(S) OR DOORS	/				20 DOOR GEAR	/			
4 LANDING GATE OR DOOR LOCKS	/				21 PUSHES & INDICATORS	/			
5 CAR GATE(S) OR DOOR LOCKS	/				22 WORM & SPUR GEARING	/			
6 OTHER GATE OR DOOR FASTENINGS	/				23 HOISTING MOTOR	/			
7 CAR OR PLATFORM FITTINGS	/				24 GENERATOR	/			
8 CAR GUIDES AND FITTINGS	/				25 CONTROLLER CONTACTS	/			
9 BUFFERS	/				26 WIRING	/			
10 OVER - RUNNING DEVICES	/				27 BRAKE & BRAKE LININGS	/			
11 SUSPENSION RODS	/				28 SELECTOR CONTACTS	/			
12 GOVERNOR ROPES	/				29 PULLEY WHEELS	/			
13 SAFETY ROPES	/				30 LIFT SHAFT SWITCHES	/			
14 SAFETY ROPES OR TAPES	/				31 RAM & CYLINDER	/			
15 SAFETY GEAR	/				32 VALVE GEAR	/			
16 OVERSPEED GOVERNOR CAR	/				33 RAM PACKINGS	/			
17 CAR SHOES OR ROLLERS	/				34 WHAT PARTS (IF ANY) INACCESSIBLE	/			

S = SATISFACTORY

WBS = WORN BUT SERVICEABLE

SBOH = SHOULD BE OVERHAULED

SBR = SHOULD BE RENEWED

TIME OF ARRIVAL \_\_\_\_\_ TIME OF DEPARTURE \_\_\_\_\_

OFFICE USE ONLY

MATERIALS

*ROUTINE VISIT*

*RECOMMENDS SHAFT + MOTOR ROOM CLEAN  
DOWN AFTER BUILDING WORK.*

ENGINEER'S REPORT / REMARKS / JHA

CUSTOMER'S SIGNATURE \_\_\_\_\_

ENGINEER'S SIGNATURE 

Express House, 100 Rolt Street, Deptford, London SE8 5NN  
Tel: \_\_\_\_\_ Fax: \_\_\_\_\_


ISO 9001  
BUREAU VERITAS  
Certification



CL80244

PDR00000047/10  
PDR00000047\_0010





Lifts for London

# ENGINEER SERVICE REPORT

Form No. 140/11 05/10

256021

EXPRESS

Lifts Alliance Group

DATE 24-11-14

ENGINEER T.F. WILLIAMS

SITE ADDRESS GRENFEL TOWER

CONTRACT No. PD807174

W11 1TG

TYPE OF MACHINE PAS-TRAC

No. OF MACHINE H090

PART	S	WBS	SBOH	SBR	PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY	/	/	/	/	18 BALANCE WEIGHT SHOES	/	/	/	/
2 LANDING GATES OR DOORS	/	/	/	/	19 CAR LANDING DOOR ACCESSORIES	/	/	/	/
3 CAR GATE(S) OR DOORS	/	/	/	/	20 DOOR GEAR	/	/	/	/
4 LANDING GATE OR DOOR LOCKS	/	/	/	/	21 PUSHES & INDICATORS	/	/	/	/
5 CAR GATE(S) OR DOOR LOCKS	/	/	/	/	22 WORM & SPUR GEARING	/	/	/	/
6 OTHER GATE OR DOOR FASTENINGS	/	/	/	/	23 HOISTING MOTOR	/	/	/	/
7 CAR OR PLATFORM FITTINGS	/	/	/	/	24 GENERATOR	/	/	/	/
8 CAR GUIDES AND FITTINGS	/	/	/	/	25 CONTROLLER CONTACTS	/	/	/	/
9 BUFFERS	/	/	/	/	26 WIRING	/	/	/	/
10 OVER - RUNNING DEVICES	/	/	/	/	27 BRAKE & BRAKE LININGS	/	/	/	/
11 SUSPENSION RODS	/	/	/	/	28 SELECTOR CONTACTS	/	/	/	/
12 GOVERNOR ROPES	/	/	/	/	29 PULLEY WHEELS	/	/	/	/
13 SAFETY ROPES	/	/	/	/	30 LIFT SHAFT SWITCHES	/	/	/	/
14 SAFETY ROPES OR TAPES	/	/	/	/	31 RAM & CYLINDER	/	/	/	/
15 SAFETY GEAR	/	/	/	/	32 VALVE GEAR	/	/	/	/
16 OVERSPEED GOVERNOR CAR	/	/	/	/	33 RAM PACKINGS	/	/	/	/
17 CAR SHOES OR ROLLERS	/	/	/	/	34 WHAT PARTS (IF ANY) INACCESSIBLE	/	/	/	/

S = SATISFACTORY WBS = WORN BUT SERVICEABLE SBOH = SHOULD BE OVERHAULED SBR = SHOULD BE RENEWED

TIME OF ARRIVAL \_\_\_\_\_ TIME OF DEPARTURE \_\_\_\_\_

OFFICE USE ONLY

MATERIALS

ENGINEER'S REPORT / REMARKS / JHA

RECOMMEND MOTOR ROOM AND SHAFT  
CLEAN DOWN DUE TO BUILDERS ON SITE

CUSTOMER'S SIGNATURE \_\_\_\_\_

ENGINEER'S SIGNATURE T.F. Williams

Express House, 100 Rolt Street, Deptford, London SE8 5NN

Tel: \_\_\_\_\_ Fax: \_\_\_\_\_



CL80244



Lifts for London

## ENGINEER SERVICE REPORT

Form No. 140/11 05/10

256094  
250094

**EXPRESS**  
Lifts Alliance  
Group

DATE 19/12/14 ENGINEER S. HAGGARTY  
SITE ADDRESS Grenfell Tower CONTRACT No. PD807174  
TYPE OF MACHINE Traction  
No. OF MACHINE H090

PART	S	WBS	SBOH	SBR	PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY	/				18 BALANCE WEIGHT SHOES	/			
2 LANDING GATES OR DOORS	/				19 CAR LANDING DOOR ACCESSORIES	/			
3 CAR GATE(S) OR DOORS	/				20 DOOR GEAR	/			
4 LANDING GATE OR DOOR LOCKS	/				21 PUSHES & INDICATORS	/			
5 CAR GATE(S) OR DOOR LOCKS	/				22 WORM & SPUR GEARING	/			
6 OTHER GATE OR DOOR FASTENINGS	/				23 HOISTING MOTOR	/			
7 CAR OR PLATFORM FITTINGS	/				24 GENERATOR	/			
8 CAR GUIDES AND FITTINGS	/				25 CONTROLLER CONTACTS	/			
9 BUFFERS	/				26 WIRING	/			
10 OVER - RUNNING DEVICES	/				27 BRAKE & BRAKE LININGS	/			
11 SUSPENSION RODS	/				28 SELECTOR CONTACTS	/			
12 GOVERNOR ROPES	/				29 PULLEY WHEELS	/			
13 SAFETY ROPES	/				30 LIFT SHAFT SWITCHES	/			
14 SAFETY ROPES OR TAPES	/				31 RAM & CYLINDER	/			
15 SAFETY GEAR	/				32 VALVE GEAR	/			
16 OVERSPEED GOVERNOR CAR	/				33 RAM PACKINGS	/			
17 CAR SHOES OR ROLLERS	/				34 WHAT PARTS (IF ANY) INACCESSIBLE	/			

S = SATISFACTORY WBS = WORN BUT SERVICEABLE SBOH = SHOULD BE OVERHAULED SBR = SHOULD BE RENEWED

TIME OF ARRIVAL \_\_\_\_\_ TIME OF DEPARTURE \_\_\_\_\_ OFFICE USE ONLY

MATERIALS

ENGINEER'S REPORT / REMARKS / JHA

Short clean down req. after major building works. Severely dusty. Gear is leaking oil and requires attention

CUSTOMER'S SIGNATURE \_\_\_\_\_ ENGINEER'S SIGNATURE [Signature]

Express House, 100 Roit Street, Deptford, London SE8 5NN  
Tel: \_\_\_\_\_ Fax: \_\_\_\_\_



CL80244





Lifts for London

# ENGINEER SERVICE REPORT

Form No. 140/11 05/10

255566  
255566

**EXPRESS**  
Lifts Alliance  
Group

DATE 31/1/15  
SITE ADDRESS Greenfell Tower

ENGINEER S. Haggarty  
CONTRACT No. D807174  
TYPE OF MACHINE Traction  
No. OF MACHINE 14090

PART	S	WBS	SBOH	SBR	PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY	/				18 BALANCE WEIGHT SHOES	/			
2 LANDING GATES OR DOORS	/				19 CAR LANDING DOOR ACCESSORIES	/			
3 CAR GATE(S) OR DOORS	/				20 DOOR GEAR	/			
4 LANDING GATE OR DOOR LOCKS	/				21 PUSHES & INDICATORS	/			
5 CAR GATE(S) OR DOOR LOCKS	/				22 WORM & SPUR GEARING	/			
6 OTHER GATE OR DOOR FASTENINGS	/				23 HOISTING MOTOR	/			
7 CAR OR PLATFORM FITTINGS	/				24 GENERATOR	/			
8 CAR GUIDES AND FITTINGS	/				25 CONTROLLER CONTACTS	/			
9 BUFFERS	/				26 WIRING	/			
10 OVER - RUNNING DEVICES	/				27 BRAKE & BRAKE LININGS	/			
11 SUSPENSION RODS	/				28 SELECTOR CONTACTS	/			
12 GOVERNOR ROPES	/				29 PULLEY WHEELS	/			
13 SAFETY ROPES	/				30 LIFT SHAFT SWITCHES	/			
14 SAFETY ROPES OR TAPES	/				31 RAM & CYLINDER	/			
15 SAFETY GEAR	/				32 VALVE GEAR	/			
16 OVERSPEED GOVERNOR CAR	/				33 RAM PACKINGS	/			
17 CAR SHOES OR ROLLERS	/				34 WHAT PARTS (IF ANY) INACCESSIBLE	/			

S = SATISFACTORY      WBS = WORN BUT SERVICEABLE      SBOH = SHOULD BE OVERHAULED      SBR = SHOULD BE RENEWED

TIME OF ARRIVAL \_\_\_\_\_ TIME OF DEPARTURE \_\_\_\_\_ OFFICE USE ONLY

MATERIALS

ENGINEER'S REPORT / REMARKS / JHA

Traces of oil around gear. Re seal is recommended. Full shaft clean down required due to ongoing building work.

CUSTOMER'S SIGNATURE \_\_\_\_\_ ENGINEER'S SIGNATURE S. Haggarty

Express House, 100 Rolt Street, Deptford, London SE8 5NN  
Tel: [redacted] Fax: [redacted]



CL80244





# ENGINEER SERVICE REPORT

Form No. 140/11 05/10

256488

200708

**EXPRESS**

Lifts Alliance Group

*Lifts for London*

DATE 28/2/15 ENGINEER SHAGGAMTY  
 SITE ADDRESS GLENFELK CONTRACT No. PD807174  
 TYPE OF MACHINE TRACTION  
 No. OF MACHINE 4090

PART	S	WBS	SBOH	SBR	PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY	/	/	/	/	18 BALANCE WEIGHT SHOES	/	/	/	/
2 LANDING GATES OR DOORS	/	/	/	/	19 CAR LANDING DOOR ACCESSORIES	/	/	/	/
3 CAR GATE(S) OR DOORS	/	/	/	/	20 DOOR GEAR	/	/	/	/
4 LANDING GATE OR DOOR LOCKS	/	/	/	/	21 PUSHES & INDICATORS	/	/	/	/
5 CAR GATE(S) OR DOOR LOCKS	/	/	/	/	22 WORM & SPUR GEARING	/	/	/	/
6 OTHER GATE OR DOOR FASTENINGS	/	/	/	/	23 HOISTING MOTOR	/	/	/	/
7 CAR OR PLATFORM FITTINGS	/	/	/	/	24 GENERATOR	/	/	/	/
8 CAR GUIDES AND FITTINGS	/	/	/	/	25 CONTROLLER CONTACTS	/	/	/	/
9 BUFFERS	/	/	/	/	26 WIRING	/	/	/	/
10 OVER - RUNNING DEVICES	/	/	/	/	27 BRAKE & BRAKE LININGS	/	/	/	/
11 SUSPENSION RODS	/	/	/	/	28 SELECTOR CONTACTS	/	/	/	/
12 GOVERNOR ROPES	/	/	/	/	29 PULLEY WHEELS	/	/	/	/
13 SAFETY ROPES	/	/	/	/	30 LIFT SHAFT SWITCHES	/	/	/	/
14 SAFETY ROPES OR TAPES	/	/	/	/	31 RAM & CYLINDER	/	/	/	/
15 SAFETY GEAR	/	/	/	/	32 VALVE GEAR	/	/	/	/
16 OVERSPEED GOVERNOR CAR	/	/	/	/	33 RAM PACKINGS	/	/	/	/
17 CAR SHOES OR ROLLERS	/	/	/	/	34 WHAT PARTS (IF ANY) INACCESSIBLE	/	/	/	/

S = SATISFACTORY WBS = WORN BUT SERVICEABLE SBOH = SHOULD BE OVERHAULED SBR = SHOULD BE RENEWED

TIME OF ARRIVAL \_\_\_\_\_ TIME OF DEPARTURE \_\_\_\_\_

OFFICE USE ONLY

## MATERIALS

Builders have been on site for sometime.  
 Full shaft clean down is required once  
 works are complete.

ENGINEER'S REPORT / REMARKS / JHA

Repairs needed to check  
 seals on gear box.

CUSTOMER'S SIGNATURE \_\_\_\_\_ ENGINEER'S SIGNATURE [Signature]

Express House, 100 Rolt Street, Deptford, London SE8 5NN  
 Tel: \_\_\_\_\_ Fax: \_\_\_\_\_



CL80244



# ENGINEER SERVICE REPORT

252730

**EXPRESS**  
Lifts Alliance  
Group

Lifts for London

DATE 25/4/15 ENGINEER S Haggarty  
SITE ADDRESS Greenfell Twn CONTRACT No. PD607174  
TYPE OF MACHINE Traction  
No. OF MACHINE H090

PART	S	WBS	SBOH	SBR	PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY	/				18 BALANCE WEIGHT SHOES	/			
2 LANDING GATES OR DOORS	/				19 CAR LANDING DOOR ACCESSORIES	/			
3 CAR GATE(S) OR DOORS	/				20 DOOR GEAR	/			
4 LANDING GATE OR DOOR LOCKS	/				21 PUSHES & INDICATORS	/			
5 CAR GATE(S) OR DOOR LOCKS	/				22 WORM & SPUR GEARING	/			
6 OTHER GATE OR DOOR FASTENINGS	/				23 HOISTING MOTOR	/			
7 CAR OR PLATFORM FITTINGS	/				24 GENERATOR	/			
8 CAR GUIDES AND FITTINGS	/				25 CONTROLLER CONTACTS	/			
9 BUFFERS	/				26 WIRING	/			
10 OVER - RUNNING DEVICES	/				27 BRAKE & BRAKE LININGS	/			
11 SUSPENSION RODS	/				28 SELECTOR CONTACTS	/			
12 GOVERNOR ROPES	/				29 PULLEY WHEELS	/			
13 SAFETY ROPES	/				30 LIFT SHAFT SWITCHES	/			
14 SAFETY ROPES OR TAPES	/				31 RAM & CYLINDER	/			
15 SAFETY GEAR	/				32 VALVE GEAR	/			
16 OVERSPEED GOVERNOR CAR	/				33 RAM PACKINGS	/			
17 CAR SHOES OR ROLLERS	/				34 WHAT PARTS (IF ANY) INACCESSIBLE	/			

S = SATISFACTORY    WBS = WORN BUT SERVICEABLE    SBOH = SHOULD BE OVERHAULED    SBR = SHOULD BE RENEWED

TIME OF ARRIVAL \_\_\_\_\_ TIME OF DEPARTURE \_\_\_\_\_ OFFICE USE ONLY

## MATERIALS

Shaft clean down ~~strongly~~ required once  
builders have finished works

## ENGINEER'S REPORT / REMARKS / JHA

Gear seal's need investigating by repair

CUSTOMER'S SIGNATURE \_\_\_\_\_ ENGINEER'S SIGNATURE S Haggarty

Express House, 100 Rolt Street, Deptford, London SE8 5NN  
Tel: \_\_\_\_\_ Fax: \_\_\_\_\_



CL80244





Lifts for London

## ENGINEER SERVICE REPORT

Form No. 140/11 05/10

251928

**EXPRESS**  
Lifts Alliance  
Group

DATE 22/5/15 ENGINEER S. Haggarty  
SITE ADDRESS Greenfell Tower CONTRACT No. PD807174  
TYPE OF MACHINE Traction  
No. OF MACHINE H090

PART	S	WBS	SBOH	SBR	PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY	/				18 BALANCE WEIGHT SHOES	/			
2 LANDING GATES OR DOORS	/				19 CAR LANDING DOOR ACCESSORIES	/			
3 CAR GATE(S) OR DOORS	/				20 DOOR GEAR	/			
4 LANDING GATE OR DOOR LOCKS	/				21 PUSHES & INDICATORS	/			
5 CAR GATE(S) OR DOOR LOCKS	/				22 WORM & SPUR GEARING	/			
6 OTHER GATE OR DOOR FASTENINGS	/				23 HOISTING MOTOR	/			
7 CAR OR PLATFORM FITTINGS	/				24 GENERATOR	/			
8 CAR GUIDES AND FITTINGS	/				25 CONTROLLER CONTACTS	/			
9 BUFFERS	/				26 WIRING	/			
10 OVER - RUNNING DEVICES	/				27 BRAKE & BRAKE LININGS	/			
11 SUSPENSION RODS	/				28 SELECTOR CONTACTS	/			
12 GOVERNOR ROPES	/				29 PULLEY WHEELS	/			
13 SAFETY ROPES	/				30 LIFT SHAFT SWITCHES	/			
14 SAFETY ROPES OR TAPES	/				31 RAM & CYLINDER	/			
15 SAFETY GEAR	/				32 VALVE GEAR	/			
16 OVERSPEED GOVERNOR CAR	/				33 RAM PACKINGS	/			
17 CAR SHOES OR ROLLERS	/				34 WHAT PARTS (IF ANY) INACCESSIBLE	/			

S = SATISFACTORY    WBS = WORN BUT SERVICEABLE    SBOH = SHOULD BE OVERHAULED    SBR = SHOULD BE RENEWED

TIME OF ARRIVAL \_\_\_\_\_ TIME OF DEPARTURE \_\_\_\_\_

OFFICE USE ONLY

### MATERIALS

Full shaft clean down is required after constant building works.

### ENGINEER'S REPORT / REMARKS / JHA

Re seal on gen is required due to leakage.  
Follow up is required for inspection

CUSTOMER'S SIGNATURE \_\_\_\_\_

ENGINEER'S SIGNATURE S. Haggarty

Express House, 100 Rolt Street, Deptford, London SE8 5NN  
Tel: \_\_\_\_\_ Fax: \_\_\_\_\_

ISO 9001  
BUREAU VERITAS  
Certification



CL80244





Lifts for London

# ENGINEER SERVICE REPORT

Form No. 140/11 05/10

255598

**EXPRESS**  
Lifts Alliance  
Group

DATE 25/6/12 ENGINEER S. Raggaby  
SITE ADDRESS Greenwich Tower CONTRACT No. PD 807174  
TYPE OF MACHINE Traction  
No. OF MACHINE H090

PART	S	WBS	SBOH	SBR	PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY	/	/	/	/	18 BALANCE WEIGHT SHOES	/	/	/	/
2 LANDING GATES OR DOORS	/	/	/	/	19 CAR LANDING DOOR ACCESSORIES	/	/	/	/
3 CAR GATE(S) OR DOORS	/	/	/	/	20 DOOR GEAR	/	/	/	/
4 LANDING GATE OR DOOR LOCKS	/	/	/	/	21 PUSHES & INDICATORS	/	/	/	/
5 CAR GATE(S) OR DOOR LOCKS	/	/	/	/	22 WORM & SPUR GEARING	/	/	/	/
6 OTHER GATE OR DOOR FASTENINGS	/	/	/	/	23 HOISTING MOTOR	/	/	/	/
7 CAR OR PLATFORM FITTINGS	/	/	/	/	24 GENERATOR	/	/	/	/
8 CAR GUIDES AND FITTINGS	/	/	/	/	25 CONTROLLER CONTACTS	/	/	/	/
9 BUFFERS	/	/	/	/	26 WIRING	/	/	/	/
10 OVER - RUNNING DEVICES	/	/	/	/	27 BRAKE & BRAKE LININGS	/	/	/	/
11 SUSPENSION RODS	/	/	/	/	28 SELECTOR CONTACTS	/	/	/	/
12 GOVERNOR ROPES	/	/	/	/	29 PULLEY WHEELS	/	/	/	/
13 SAFETY ROPES	/	/	/	/	30 LIFT SHAFT SWITCHES	/	/	/	/
14 SAFETY ROPES OR TAPES	/	/	/	/	31 RAM & CYLINDER	/	/	/	/
15 SAFETY GEAR	/	/	/	/	32 VALVE GEAR	/	/	/	/
16 OVERSPEED GOVERNOR CAR	/	/	/	/	33 RAM PACKINGS	/	/	/	/
17 CAR SHOES OR ROLLERS	/	/	/	/	34 WHAT PARTS (IF ANY) INACCESSIBLE	/	/	/	/

S = SATISFACTORY WBS = WORN BUT SERVICEABLE SBOH = SHOULD BE OVERHAULED SBR = SHOULD BE RENEWED

TIME OF ARRIVAL \_\_\_\_\_ TIME OF DEPARTURE \_\_\_\_\_

OFFICE USE ONLY

## MATERIALS

Gear box leaking. Investigation req.

Shaft clean down needed once builders are off site

ENGINEER'S REPORT / REMARKS / JHA

CUSTOMER'S SIGNATURE \_\_\_\_\_

ENGINEER'S SIGNATURE [Signature]

Express House, 100 Rolt Street, Deptford, London SE8 5NN  
Tel: \_\_\_\_\_ Fax: \_\_\_\_\_



CL80244

EXPRESS

# Service Visit Report



## Lifts Alliance Group

Registered in London No. 147366 and Jersey No. 0008376  
Registered Office, Chiswick Park Building 5, Ground Floor, 566 Chiswick High Road, W4 5YF

Service and breakdown  
London & South East: [REDACTED]  
All Other UK Regions: [REDACTED]

Visit Type M  
Unit Number PD807174  
Customer Order No.

CALLBACK/REPAIR No.   
Misuse (Y/N) ☐ Completed (Y/N) ☐  
Accidental Damage (Y/N) ☐ Shutdown (Y/N) ☐

Site Address

GLENEEL TOWER

Unit Type/Customer Unit Reference H090 Customer Name TMO

Maintenance Activity Report (✓ as applicable)

	Checked		Serviceable	
	Y	Not Fitted	Y	N
Car Operating Panel/s	✓		✓	
Car Lighting	✓		✓	
Emergency Alarm Systems	✓		✓	
Hall Buttons / Indicators	✓		✓	
Floor Levels	✓		✓	
Controller / Drive	✓		✓	
Brake	✓		✓	
Machine / Hydro Power Unit	✓		✓	
Overspeed Devices	✓		✓	
Operation of Car Doors	✓		✓	
Car Top	✓		✓	

	Checked		Serviceable	
	Y	Not Fitted	Y	N
Landing Doors	✓		✓	
Counterweight / RAM	✓		✓	
Main Suspension Check	✓		✓	
Pit Area	✓		✓	
Annual / 4 Year Checks				
Door Check				
Suspension Check				
RA Review				
Elec & Mech Check				
Earth Continuity Test				
Brake Check				

Scope of Work & Materials Used (quoting part number where possible)


Observations

BUILDERS ON SITE, FULL SHAFT CLEAN DOWN REQUIRED ONCE WORKS ARE COMPLETE

	Engineer's Name (Please print clearly)	Employee Number	Arrival Time	Depart Time	Total Site Hours	Travel Hours
Engineer 1	S. HACCARTY	58388	:	:	:	:
Engineer 2	T. WILLIAMS	58512	:	:	:	:

Date:	Customer's Name:	Customer's Signature:
-------	------------------	-----------------------

Top Copy: Customer Second Copy: Office



Lifts Alliance  
GroupRegistered in London No. 147366 and Jersey No. 0008376  
Registered Office, Chiswick Park Building 5, Ground Floor, 566 Chiswick High Road, W4 5YFService and breakdown  
London & South East: [REDACTED]  
All Other UK Regions: [REDACTED]Visit Type M  
Unit Number PD807174  
Customer Order No.                       
Site Address GRENFELLCALLBACK/REPAIR No.                       
Misuse (Y / N) ☐ Completed (Y / N) ☐  
Accidental Damage (Y / N) ☐ Shutdown (Y / N) ☐Unit Type/Customer Unit Reference H090 Customer Name TMO

## Maintenance Activity Report (✓ as applicable)

	Checked		Serviceable	
	Y	Not Fitted	Y	N
Car Operating Panel/s	/		/	
Car Lighting	/		/	
Emergency Alarm Systems	/		/	
Hall Buttons / Indicators	/		/	
Floor Levels	/		/	
Controller / Drive	/		/	
Brake	/		/	
Machine / Hydro Power Unit	/		/	
Overspeed Devices	/		/	
Operation of Car Doors	/		/	
Car Top	/		/	

	Checked		Serviceable	
	Y	Not Fitted	Y	N
Landing Doors	/		/	
Counterweight / RAM	/		/	
Main Suspension Check	/		/	
Pit Area	/		/	
Annual / 4 Year Checks				
Door Check				
Suspension Check				
RA Review				
Elec & Mech Check				
Earth Continuity Test				
Brake Check				

## Scope of Work &amp; Materials Used (quoting part number where possible)


## Observations

Short clean down required once builders have finished works

	Engineer's Name (Please print clearly)	Employee Number	Arrival Time	Depart Time	Total Site Hours	Travel Hours
Engineer 1	S. HAGGARTY	58388	:	:	:	:
Engineer 2	T. WILLIAMS	58512	:	:	:	:

Date: 20/08/15	Customer's Name:	Customer's Signature:
-------------------	------------------	-----------------------

Top Copy: Customer    Second Copy: Office

78.9.49.477(03.14)



# Service Visit Report



Lifts Alliance  
Group

Registered in London No. 147366 and Jersey No. 0008376  
Registered Office, Chiswick Park Building 5, Ground Floor, 566 Chiswick High Road, W4 5YF

Service and breakdown  
London & South East: [REDACTED]  
All Other UK Regions: [REDACTED]

Visit Type   
Unit Number   
Customer Order No.   
Site Address

CALLBACK/REPAIR No.   
Misuse (Y / N) ☐ Completed (Y / N) ☐  
Accidental Damage (Y / N) ☐ Shutdown (Y / N) ☐

Site Address

Unit Type/Customer Unit Reference  Customer Name

Maintenance Activity Report (✓ as applicable)

	Checked		Serviceable	
	Y	Not Fitted	Y	N
Car Operating Panel/s	✓		✓	
Car Lighting	✓		✓	
Emergency Alarm Systems	✓		✓	
Hall Buttons / Indicators	✓		✓	
Floor Levels	✓		✓	
Controller / Drive	✓		✓	
Brake	✓		✓	
Machine / Hydro Power Unit	✓		✓	
Overspeed Devices	✓		✓	
Operation of Car Doors	✓		✓	
Car Top	✓		✓	

	Checked		Serviceable	
	Y	Not Fitted	Y	N
Landing Doors	✓		✓	
Counterweight / RAM	✓		✓	
Main Suspension Check	✓		✓	
Pit Area	✓		✓	
Annual / 4 Year Checks				
Door Check				
Suspension Check				
RA Review				
Elec & Mech Check				
Earth Continuity Test				
Brake Check				

Scope of Work & Materials Used (quoting part number where possible)

Observations

	Engineer's Name (Please print clearly)	Employee Number	Arrival Time	Depart Time	Total Site Hours	Travel Hours
Engineer 1	S. HAGGARTY	S 8388	:	:	:	:
Engineer 2	T. WILLIAMS	S 8512	:	:	:	:

Date:  Customer's Name:  Customer's Signature:

Top Copy: Customer    Second Copy: Office

78.9.49.477(05.14)



<b>Job Number</b>	PD807174
<b>Unit Number</b>	PD807174
<b>Site Address</b>	Grenfell Tower Grenfell Road London W11 1TG
<b>Unit Reference</b>	H090
<b>Date of Service Visit Report</b>	04/11/2015
<b>Visit Type</b>	M2

<b>Customer Order Number</b>	
<b>Parts Used</b>	

<b>Works Completed</b>
As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :
<ul style="list-style-type: none"> <li>Car Enclosure and COP</li> <li>Emergency Alarm System</li> <li>Indicators and Call Buttons</li> <li>Floor Levels and Selector</li> <li>Machine and Brake</li> <li>Controller and Drive</li> <li>Overspeed Devices</li> <li>Operation of Car Doors</li> <li>Car Top</li> <li>Door and Gate Check</li> <li>Shaft Equipment</li> <li>Pit and Underside of Car</li> <li>Annual Main Suspension Check</li> <li>Annual Door Check</li> <li>Electrical Safety Switch Check</li> <li>Annual Brake Check</li> </ul>

<b>Observations</b>
full shaft cleandown requied once builders have completed works seals leaking slightly on gear

<b>Total Time on Site</b>	1.30
<b>Total Travel to Site</b>	0.00

<b>Customer Name</b>	<b>Customer Unavailable For Signature</b>
<b>Signed Date &amp; Time</b>	

<b>Signature Declined</b>	N
<b>Decline Reason</b>	

Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
S Haggarty (58388)	28/10/15	11:00	12:30	1.30	0.00	N/A

Job Number	PD807174
Unit Number	PD807174
Site Address	Grenfell Tower Grenfell Road London W11 1TG
Unit Reference	H090
Date of Service Visit Report	26/11/2015
Visit Type	M2

Customer Order Number	
Parts Used	

Works Completed
As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :
<ul style="list-style-type: none"> <li>Car Enclosure and COP</li> <li>Emergency Alarm System</li> <li>Indicators and Call Buttons</li> <li>Floor Levels and Selector</li> <li>Machine and Brake</li> <li>Controller and Drive</li> <li>Overspeed Devices</li> <li>Operation of Car Doors</li> <li>Car Top</li> <li>Door and Gate Check</li> <li>Shaft Equipment</li> <li>Pit and Underside of Car</li> </ul>

Observations
full shaft cleandown requied once builders have completed works seals leaking slightly on gear door operator needs setting up once builders have completed works still no phonline in lift

Total Time on Site	1.30
--------------------	------

Total Travel to Site	0.00
----------------------	------

Customer Name	Customer Unavailable For Signature
Signed Date & Time	

Signature Declined	N
Decline Reason	

Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
S Haggarty (58388)	26/11/15	08:00	09:30	1.30	0.00	N/A



Job Number PD807174

Unit Number PD807174

Site Address  
Grenfell Tower  
Grenfell Road  
London W11 1TG

Unit Reference H090

Date of Service Visit Report 27/01/2016

Visit Type M2

**Works Completed**

As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :

Car Enclosure and COP  
Emergency Alarm System  
Indicators and Call Buttons  
Floor Levels and Selector  
Machine and Brake  
Controller and Drive  
Overspeed Devices  
Operation of Car Doors  
Car Top  
Door and Gate Check  
Shaft Equipment  
Pit and Underside of Car

Signature Declined N

Decline Reason

**Attending Engineer(s)**

Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
S Haggarty (58388)	25/01/16	08:00	09:15	1.15	0.00	N/A

ELA Group  
A division of Otis Ltd registered in England and Wales, No 147366  
Registered Office: Chiswick Park, Building 5 Ground Floor, 566 Chiswick High Road, London W4 5YF

Customer Order Number

**Parts Used**

**Observations**

full shaft cleandown requied once builders have completed works seals leaking slightly on gear door operator needs setting up once builders have completed works still no phonline in lift

Total Time on Site 1.15

Total Travel to Site 0.00

Customer Name

Signed Date & Time

**Customer  
Unavailable  
For Signature**

Job Number	PD807174
Unit Number	PD807174
Site Address	Grenfell Tower Grenfell Road London W11 1TG
Unit Reference	H090
Date of Service Visit Report	25/02/2016
Visit Type	S

Customer Order Number	
Parts Used	

Works Completed
As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :
<ul style="list-style-type: none"> <li>Car Enclosure and COP</li> <li>Emergency Alarm System</li> <li>Indicators and Call Buttons</li> <li>Floor Levels and Selector</li> <li>Machine and Brake</li> <li>Controller and Drive</li> <li>Overspeed Devices</li> <li>Operation of Car Doors</li> <li>Car Top</li> <li>Door and Gate Check</li> <li>Shaft Equipment</li> <li>Pit and Underside of Car</li> <li>Annual Main Suspension Check</li> <li>Annual Door Check</li> <li>Electrical Safety Switch Check</li> <li>Annual Brake Check</li> </ul>

Observations
full shaft cleandown requied once builders have completed works seals leaking slightly on gear door operator needs setting up once builders have completed works still no phonline in lift

Total Time on Site	1.30
--------------------	------

Total Travel to Site	0.00
----------------------	------

Customer Name	Customer Unavailable For Signature
Signed Date & Time	

Signature Declined	N
Decline Reason	

Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
S Haggarty (58388)	19/02/16	08:00	09:30	1.30	0.00	N/A



Job Number PD807174

Unit Number PD807174

Site Address  
Grenfell Tower  
Grenfell Road  
London W11 1TG

Unit Reference H090

Date of Service Visit Report 26/05/2016

Visit Type M2

Works Completed

As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :

Car Enclosure and COP  
Emergency Alarm System  
Indicators and Call Buttons  
Floor Levels and Selector  
Machine and Brake  
Controller and Drive  
Overspeed Devices  
Operation of Car Doors  
Car Top  
Door and Gate Check  
Shaft Equipment  
Pit and Underside of Car

Customer Order Number

Parts Used

Observations

full shaft cleandown requied once builders have completed works. seals leaking slightly on gear. door operator needs setting up once builders have completed works. there is an earth on thr ground floor display which is blowing fuses in the psu2unit. contractors have glued display plate to wall and will create damage to wall. custmer action required

Total Time on Site 1.00

Total Travel to Site 0.00

Customer Name

Signed Date & Time

**Customer  
Unavailable  
For Signature**

Signature Declined N

Decline Reason

Attending Engineer(s)

Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
S Haggarty (58388)	25/05/16	10:00	11:00	1.00	0.00	N/A

Job Number PD807174

Unit Number PD807174

Site Address  
Grenfell Tower  
Grenfell Road  
London W11 1TG

Unit Reference H090

Date of Service Visit Report 11/07/2016

Visit Type M2

**Works Completed**

As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :

Car Enclosure and COP  
Emergency Alarm System  
Indicators and Call Buttons  
Floor Levels and Selector  
Machine and Brake  
Controller and Drive  
Overspeed Devices  
Operation of Car Doors  
Car Top  
Door and Gate Check  
Shaft Equipment  
Pit and Underside of Car

Signature Declined N

Decline Reason

**Attending Engineer(s)**

Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
S Haggarty (58388)	29/06/16	15:00	16:00	1.00	0.00	N/A

ELA Group  
A division of Otis Ltd registered in England and Wales, No 147366  
Registered Office: Chiswick Park, Building 5 Ground Floor, 566 Chiswick High Road, London W4 5YF

Customer Order Number

**Parts Used**

**Observations**

full shaft cleandown required once builders have completed works. seals leaking slightly on gear. door operator needs setting up once builders have completed works. there is an earth on the ground floor display which is blowing fuses in the psu2unit. contractors have glued display plate to wall and will create damage to wall. customer action required

Total Time on Site 1.00

Total Travel to Site 0.00

Customer Name

Signed Date & Time

**Customer  
Unavailable  
For Signature**



Job Number PD807174

Unit Number PD807174

Site Address  
Grenfell Tower  
Grenfell Road  
London W11 1TG

Unit Reference H090

Date of Service Visit Report 18/10/2016

Visit Type M2

**Works Completed**

As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :

Car Enclosure and COP  
Emergency Alarm System  
Indicators and Call Buttons  
Floor Levels and Selector  
Machine and Brake  
Operation of Car Doors  
Car Top  
Shaft Equipment

Signature Declined N

Decline Reason

**Attending Engineer(s)**

Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
D Smalley (55029)	18/10/16	08:00	10:01	2.01	0.00	N/A

Customer Order Number

**Parts Used**

**Observations**

full shaft cleandown requied once builders have completed works. seals leaking slightly on gear. door operator needs setting up once builders have completed works. there is an earth on thr ground floor display which is blowing fuses in the psu2unit. contractors have glued display plate to wall and will create damage to wall. customer action required new car door hanger rollers have been fitted. recommend car lighting and car fan have a separate feed

Total Time on Site 2.01

Total Travel to Site 0.00

Customer Name

Signed Date & Time

**Customer  
Unavailable  
For Signature**

PDR00000047/28  
PDR00000047 0020



Job Number PD807174

Unit Number PD807174

Site Address  
Grenfell Tower  
Grenfell Road  
London W11 1TG

Unit Reference H090

Date of Service Visit Report 05/01/2017

Visit Type S

**Works Completed**

As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :

Car Enclosure and COP  
Emergency Alarm System  
Indicators and Call Buttons  
Floor Levels and Selector  
Machine and Brake  
Operation of Car Doors  
Car Top  
Shaft Equipment

Signature Declined N

Decline Reason

**Attending Engineer(s)**

Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
D Smalley (55029)	05/01/17	08:00	10:00	2.00	0.00	N/A

ELA Group  
A division of Otis Ltd registered in England and Wales, No 147366  
Registered Office: Chiswick Park, Building 5 Ground Floor, 566 Chiswick High Road, London W4 5YF

Customer Order Number

**Parts Used**

**Observations**

full shaft cleandown requied once builders have completed works. seals leaking slightly on gear. door operator needs setting up once builders have completed works. there is an earth on thr ground floor display which is blowing fuses in the psu2unit. contractors have glued display plate to wall and will create damage to wall. custmer action required new car door hanger rollers have been fitted. recommend lg1 car lighting and car fan have a separate feed lg1 done nov visit dec visit

Total Time on Site 2.00

Total Travel to Site 0.00

Customer Name

Signed Date & Time

**Customer  
Unavailable  
For Signature**

<b>Job Number</b>	PD807174
<b>Unit Number</b>	PD807174
<b>Site Address</b>	Grenfell Tower Grenfell Road London W11 1TG
<b>Unit Reference</b>	H090
<b>Date of Service Visit Report</b>	18/01/2017
<b>Visit Type</b>	M2

<b>Customer Order Number</b>	
<b>Parts Used</b>	

<b>Works Completed</b>
As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :
<ul style="list-style-type: none"> <li>Car Enclosure and COP</li> <li>Emergency Alarm System</li> <li>Indicators and Call Buttons</li> <li>Floor Levels and Selector</li> <li>Machine and Brake</li> <li>Operation of Car Doors</li> <li>Car Top</li> </ul>

<b>Observations</b>
full shaft cleandown requied once builders have completed works. seals leaking slightly on gear. door operator needs setting up once builders have completed works. there is an earth on thr ground floor display which is blowing fuses in the psu2unit. contractors have glued display plate to wall and will create damage to wall. customer action required new car door hanger rollers have been fitted. recommend lg1 car lighting and car fan have a separate feed lg1 done nov visit dec visit

<b>Total Time on Site</b>	1.45
---------------------------	------

<b>Total Travel to Site</b>	0.15
-----------------------------	------

<b>Customer Name</b>	<b>Customer Unavailable For Signature</b>
<b>Signed Date &amp; Time</b>	

<b>Signature Declined</b>	N
<b>Decline Reason</b>	

Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
D Smalley (55029)	18/01/17	08:15	10:00	1.45	0.15	N/A



Job Number PD807174

Unit Number PD807174

Site Address  
Grenfell Tower  
Grenfell Road  
London W11 1TG

Unit Reference H090

Date of Service Visit Report 20/02/2017

Visit Type S

**Works Completed**

As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :

Car Enclosure and COP  
Emergency Alarm System  
Indicators and Call Buttons  
Floor Levels and Selector  
Machine and Brake  
Operation of Car Doors  
Car Top  
Shaft Equipment

Signature Declined N

Decline Reason

Customer Order Number

**Parts Used**

**Observations**

full shaft cleandown required once builders have completed works. seals leaking slightly on gear. door operator needs setting up once builders have completed works. there is an earth on thr ground floor display which is blowing fuses in the psu2unit. contractors have glued display plate to wall and will create damage to wall. customer action required new car door hanger rollers have been fitted. recommend lg1 car lighting and car fan have a separate feed lg1 done nov visit dec visit

Total Time on Site 1.45

Total Travel to Site 0.15

Customer Name

Signed Date & Time

**Customer  
Unavailable  
For Signature**

**Attending Engineer(s)**

Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
D Smalley (55029)	30/11/16	12:15	14:00	1.45	0.15	N/A

Job Number PD807174

Unit Number PD807174

Site Address  
Grenfell Tower  
Grenfell Road  
London W11 1TG

Unit Reference H090

Date of Service Visit Report 08/03/2017

Visit Type M2

**Works Completed**

As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :

Car Enclosure and COP  
Emergency Alarm System  
Indicators and Call Buttons  
Floor Levels and Selector  
Machine and Brake  
Operation of Car Doors  
Car Top  
Shaft Equipment  
Pit and Underside of Car

Signature Declined N

Decline Reason

**Attending Engineer(s)**

Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
D Smalley (55029)	08/03/17	08:00	10:00	2.00	0.00	N/A

Customer Order Number

**Parts Used**

**Observations**

full shaft cleandown requied once builders have completed works. seals leaking slightly on gear. door operator needs setting up once builders have completed works. there is an earth on thr ground floor display which is blowing fuses in the psu2unit. contractors have glued display plate to wall and will create damage to wall. custmer action required new car door hanger rollers have been fitted. recommend lg1 car lighting and car fan have a separate feed lg1 done nov visit dec visit

Total Time on Site 2.00

Total Travel to Site 0.00

Customer Name

Signed Date & Time

**Customer  
Unavailable  
For Signature**



Job Number PD807174

Unit Number PD807174

Site Address  
Grenfell Tower  
Grenfell Road  
London W11 1TG

Unit Reference H090

Date of Service Visit Report 20/03/2017

Visit Type M2

Works Completed

As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :

Car Enclosure and COP  
Emergency Alarm System  
Indicators and Call Buttons  
Floor Levels and Selector  
Machine and Brake  
Controller and Drive  
Overspeed Devices  
Operation of Car Doors  
Car Top  
Door and Gate Check  
Shaft Equipment  
Pit and Underside of Car

Signature Declined N

Decline Reason

Customer Order Number

Parts Used

Observations

Total Time on Site 1.30

Total Travel to Site 0.00

Customer Name

Signed Date & Time

**Customer  
Unavailable  
For Signature**

Attending Engineer(s)

Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
T Parker (58461)	11/02/17	08:00	09:30	1.30	0.00	N/A

Job Number PD807174

Unit Number PD807174

Site Address  
Grenfell Tower  
Grenfell Road  
London W11 1TG

Unit Reference H090

Date of Service Visit Report 27/04/2017

Visit Type M2

Works Completed

As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :

Car Enclosure and COP  
Emergency Alarm System  
Indicators and Call Buttons  
Floor Levels and Selector  
Machine and Brake  
Controller and Drive  
Overspeed Devices  
Operation of Car Doors  
Car Top  
Door and Gate Check  
Shaft Equipment  
Pit and Underside of Car

Signature Declined N

Decline Reason

Attending Engineer(s)

Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
A Smart (58579)	12/04/17	10:00	12:00	2.00	0.00	N/A

Customer Order Number

Parts Used

Observations

seals leaking slightly on gear. door operator needs setting up once builders have completed works. contractors have glued display plate to wall and will create damage to wall. customer action recommend lg1 car lighting and car fan have a separate feed lg1 done nov visit dec visit. unit requires pit ladder

Total Time on Site 2.00

Total Travel to Site 0.00

Customer Name

Signed Date & Time

Customer  
Unavailable  
For Signature



