

IN A MATTER CONCERNING THE GRENFELL TOWER INQUIRY

EXHIBIT MFT/6



ENGINEER SERVICE REPORT

Form No. 140/11 05/10

245365

EXPRESS

Lifts Alliance Group

Lifts for London

DATE 26/2/14

ENGINEER D LINNEY

SITE ADDRESS GENEVEE TOWER

CONTRACT No. PD807176

TYPE OF MACHINE TRACTION

No. OF MACHINE H090

PART	S	WBS	SBOH	SBR	PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY		/			18 BALANCE WEIGHT SHOES		/		
2 LANDING GATES OR DOORS		/			19 CAR LANDING DOOR ACCESSORIES		/		
3 CAR GATE(S) OR DOORS		/			20 DOOR GEAR		/		
4 LANDING GATE OR DOOR LOCKS		/			21 PUSHES & INDICATORS		/		
5 CAR GATE(S) OR DOOR LOCKS		/			22 WORM & SPUR GEARING		/		
6 OTHER GATE OR DOOR FASTENINGS		/			23 HOISTING MOTOR		/		
7 CAR OR PLATFORM FITTINGS		/			24 GENERATOR		/		
8 CAR GUIDES AND FITTINGS		/			25 CONTROLLER CONTACTS		/		
9 BUFFERS		/			26 WIRING		/		
10 OVER - RUNNING DEVICES		/			27 BRAKE & BRAKE LININGS		/		
11 SUSPENSION RODS		/			28 SELECTOR CONTACTS		/		
12 GOVERNOR ROPES		/			29 PULLEY WHEELS		/		
13 SAFETY ROPES		/			30 LIFT SHAFT SWITCHES		/		
14 SAFETY ROPES OR TAPES		/			31 RAM & CYLINDER		/		
15 SAFETY GEAR		/			32 VALVE GEAR		/		
16 OVERSPEED GOVERNOR CAR		/			33 RAM PACKINGS		/		
17 CAR SHOES OR ROLLERS		/			34 WHAT PARTS (IF ANY) INACCESSIBLE		/		

S = SATISFACTORY WBS = WORN BUT SERVICEABLE SBOH = SHOULD BE OVERHAULED SBR = SHOULD BE RENEWED

TIME OF ARRIVAL _____ TIME OF DEPARTURE _____

MATERIALS

ROUTINE VISIT

OFFICE USE ONLY

ENGINEER'S REPORT / REMARKS / JHA

CUSTOMER'S SIGNATURE _____ ENGINEER'S SIGNATURE _____

Express House, 100 Rolt Street, Deptford, London SE8 5NN
Tel: _____ Fax: _____



CL80244



Lifts for London

ENGINEER SERVICE REPORT

230336

THE
EXPRESS
LIFTS ALLIANCE

DATE 26 3 14

ENGINEER E J DEACON

SITE ADDRESS GREENEFULL

CONTRACT No. PP807174

TYPE OF MACHINE PAS-TH4c

No. OF MACHINE H174

PART	S	WBS	SBON	SBR	PART	S	WBS	SBON	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY	/				18 BALANCE WEIGHT SHOES	/			
2 LANDING GATES OR DOORS	/				19 CAR LANDING DOOR ACCESSORIES	/			
3 CAR GATE(S) OR DOORS	/				20 DOOR GEAR	/			
4 LANDING GATE OR DOOR LOCKS	/				21 PUSHES & INDICATORS	/			
5 CAR GATE(S) OR DOOR LOCKS	/				22 WORM & SPUR GEARING	/			
6 OTHER GATE OR DOOR FASTENINGS	/				23 HOISTING MOTOR	/			
7 CAR OR PLATFORM FITTINGS	/				24 GENERATOR	/			
8 CAR GUIDES AND FITTINGS	/				25 CONTROLLER CONTACTS	/			
9 BUFFERS	/				26 WIRING	/			
10 OVER - RUNNING DEVICES	/				27 BRAKE & BRAKE LININGS	/			
11 SUSPENSION RODS	/				28 SELECTOR CONTACTS	/			
12 GOVERNOR ROPES	/				29 PULLEY WHEELS	/			
13 SAFETY ROPES	/				30 LIFT SHAFT SWITCHES	/			
14 SAFETY ROPES OR TAPES	/				31 RAM & CYLINDER	/			
15 SAFETY GEAR	/				32 VALVE GEAR	/			
16 OVERSPEED GOVERNOR CAR	/				33 RAM PACKINGS	/			
17 CAR SHOES OR ROLLERS	/				34 WHAT PARTS (IF ANY) INACCESSIBLE	/			

S = SATISFACTORY WBS = WORN BUT SERVICEABLE SBON = SHOULD BE OVERHAULED SBR = SHOULD BE RENEWED

TIME OF ARRIVAL _____

TIME OF DEPARTURE _____

OFFICE USE ONLY

MATERIALS

ENGINEER'S REPORT / REMARKS / JHA

CUSTOMER'S SIGNATURE _____

ENGINEER'S SIGNATURE E J Deacon

PDERS Unit 6, Bermondsey Trading Estate, Rotherhithe New Road, London SE16 3LL
Tel: _____ Fax: _____



CL02244



Lifts for London

ENGINEER SERVICE REPORT

244269

EXPRESS
 Lifts Alliance
 Group

DATE 26-04-14

ENGINEER J. H. A. K. E.

SITE ADDRESS GRENFELL TOWER

CONTRACT No. PD. 837174

TYPE OF MACHINE PAS-TRAC

No. OF MACHINE 11090

W. W. 111. I T G

PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY		/		
2 LANDING GATES OR DOORS		/		
3 CAR GATE(S) OR DOORS		/		
4 LANDING GATE OR DOOR LOCKS		/		
5 CAR GATE(S) OR DOOR LOCKS		/		
6 OTHER GATE OR DOOR FASTENINGS		/		
7 CAR OR PLATFORM FITTINGS		/		
8 CAR GUIDES AND FITTINGS		/		
9 BUFFERS		/		
10 OVER - RUNNING DEVICES		/		
11 SUSPENSION RODS		/		
12 GOVERNOR ROPES		/		
13 SAFETY ROPES		/		
14 SAFETY ROPES OR TAPES		/		
15 SAFETY GEAR		/		
16 OVERSPEED GOVERNOR CAR		/		
17 CAR SHOES OR ROLLERS		/		

PART	S	WBS	SBOH	SBR
18 BALANCE WEIGHT SHOES		/		
19 CAR LANDING DOOR ACCESSORIES		/		
20 DOOR GEAR		/		
21 PUSHES & INDICATORS		/		
22 WORM & SPUR GEARING		/		
23 HOISTING MOTOR		/		
24 GENERATOR		/		
25 CONTROLLER CONTACTS		/		
26 WIRING		/		
27 BRAKE & BRAKE LININGS		/		
28 SELECTOR CONTACTS		/		
29 PULLEY WHEELS		/		
30 LIFT SHAFT SWITCHES		/		
31 RAM & CYLINDER		/		
32 VALVE GEAR		/		
33 RAM PACKINGS		/		
34 WHAT PARTS (IF ANY) INACCESSIBLE		/		

S = SATISFACTORY

WBS = WORN BUT SERVICEABLE

SBOH = SHOULD BE OVERHAULED

SBR = SHOULD BE RENEWED

TIME OF ARRIVAL

TIME OF DEPARTURE

OFFICE USE ONLY

MATERIALS

ENGINEER'S REPORT / REMARKS / JHA

CUSTOMER'S SIGNATURE

ENGINEER'S SIGNATURE

Express House, 100 Rolt Street, Deptford, London SE8 5NN

Tel: Fax:

ISO 9001
BUREAU VERITAS
Certification

CL90244



ENGINEER SERVICE REPORT

Form No. 140/11 05/10

245161

EXPRESS

Lifts Alliance Group

Lifts for London

DATE 29/5/14
SITE ADDRESS GREENFELL TOWER

ENGINEER D. LINNLEY
CONTRACT No. P0807174
TYPE OF MACHINE TRACTION
No. OF MACHINE H090

PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2 LANDING GATES OR DOORS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3 CAR GATE(S) OR DOORS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4 LANDING GATE OR DOOR LOCKS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5 CAR GATE(S) OR DOOR LOCKS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6 OTHER GATE OR DOOR FASTENINGS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7 CAR OR PLATFORM FITTINGS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8 CAR GUIDES AND FITTINGS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9 BUFFERS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10 OVER - RUNNING DEVICES	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11 SUSPENSION RODS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12 GOVERNOR ROPES	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13 SAFETY ROPES	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14 SAFETY ROPES OR TAPES	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15 SAFETY GEAR	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16 OVERSPEED GOVERNOR CAR	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17 CAR SHOES OR ROLLERS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

PART	S	WBS	SBOH	SBR
18 BALANCE WEIGHT SHOES	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19 CAR LANDING DOOR ACCESSORIES	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20 DOOR GEAR	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21 PUSHES & INDICATORS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22 WORM & SPUR GEARING	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
23 HOISTING MOTOR	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
24 GENERATOR	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
25 CONTROLLER CONTACTS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
26 WIRING	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
27 BRAKE & BRAKE LININGS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
28 SELECTOR CONTACTS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
29 PULLEY WHEELS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
30 LIFT SHAFT SWITCHES	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
31 RAM & CYLINDER	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
32 VALVE GEAR	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
33 RAM PACKINGS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
34 WHAT PARTS (IF ANY) INACCESSIBLE	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

S = SATISFACTORY

WBS = WORN BUT SERVICEABLE

SBOH = SHOULD BE OVERHAULED

SBR = SHOULD BE RENEWED

TIME OF ARRIVAL _____

TIME OF DEPARTURE _____

OFFICE USE ONLY

MATERIALS

ROUTINE VISIT

ENGINEER'S REPORT / REMARKS / JHA

[Signature]

CUSTOMER'S SIGNATURE _____

ENGINEER'S SIGNATURE _____

Express House, 100 Rolt Street, Deptford, London SE8 5NN

Tel: _____

Fax: _____

ISO 9001
BUREAU VERITAS
Certification



CLB0244

PDR00000047/5

PDR00000047 0005



ENGINEER SERVICE REPORT

Form No. 140/11 05/10

245197

EXPRESS
Lifts Alliance Group

Lifts for London

DATE

25/6/14

ENGINEER

D. Linn

SITE ADDRESS

Greenfell tower

CONTRACT No.

P0807174

TYPE OF MACHINE

TRACTION

No. OF MACHINE

12090

PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY		/		
2 LANDING GATES OR DOORS		/		
3 CAR GATE(S) OR DOORS		/		
4 LANDING GATE OR DOOR LOCKS		/		
5 CAR GATE(S) OR DOOR LOCKS		/		
6 OTHER GATE OR DOOR FASTENINGS		/		
7 CAR OR PLATFORM FITTINGS		/		
8 CAR GUIDES AND FITTINGS		/		
9 BUFFERS		/		
10 OVER - RUNNING DEVICES		/		
11 SUSPENSION RODS		/		
12 GOVERNOR ROPES		/		
13 SAFETY ROPES		/		
14 SAFETY ROPES OR TAPES		/		
15 SAFETY GEAR		/		
16 OVERSPEED GOVERNOR CAR		/		
17 CAR SHOES OR ROLLERS		/		

PART	S	WBS	SBOH	SBR
18 BALANCE WEIGHT SHOES		/		
19 CAR LANDING DOOR ACCESSORIES		/		
20 DOOR GEAR		/		
21 PUSHES & INDICATORS		/		
22 WORM & SPUR GEARING		/		
23 HOISTING MOTOR		/		
24 GENERATOR		/		
25 CONTROLLER CONTACTS		/		
26 WIRING		/		
27 BRAKE & BRAKE LININGS		/		
28 SELECTOR CONTACTS		/		
29 PULLEY WHEELS		/		
30 LIFT SHAFT SWITCHES		/		
31 RAM & CYLINDER		/		
32 VALVE GEAR		/		
33 RAM PACKINGS		/		
34 WHAT PARTS (IF ANY) INACCESSIBLE		/		

S = SATISFACTORY

WBS = WORN BUT SERVICEABLE

SBOH = SHOULD BE OVERHAULED

SBR = SHOULD BE RENEWED

TIME OF ARRIVAL

TIME OF DEPARTURE

OFFICE USE ONLY

MATERIALS

ROUTINE - VISIT

ENGINEER'S REPORT / REMARKS / JHA

CUSTOMER'S SIGNATURE

ENGINEER'S SIGNATURE

Express House, 100 Rolt Street, Deptford, London SE8 5NN

Tel: Fax:

ISO 9001
BUREAU VERITAS
Certification



CLB0244



ENGINEER SERVICE REPORT

Form No. 140/11 05/10

247944

EXPRESS

Lifts Alliance Group

Lifts for London

DATE 28/7/14

ENGINEER D. LINNBY

SITE ADDRESS GREENFELT TOWER

CONTRACT No. P0807174

TYPE OF MACHINE TRACTION

No. OF MACHINE H090

PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY		/		
2 LANDING GATES OR DOORS		/		
3 CAR GATE(S) OR DOORS		/		
4 LANDING GATE OR DOOR LOCKS		/		
5 CAR GATE(S) OR DOOR LOCKS		/		
6 OTHER GATE OR DOOR FASTENINGS		/		
7 CAR OR PLATFORM FITTINGS		/		
8 CAR GUIDES AND FITTINGS		/		
9 BUFFERS		/		
10 OVER - RUNNING DEVICES		/		
11 SUSPENSION RODS		/		
12 GOVERNOR ROPES		/		
13 SAFETY ROPES		/		
14 SAFETY ROPES OR TAPES		/		
15 SAFETY GEAR		/		
16 OVERSPEED GOVERNOR CAR		/		
17 CAR SHOES OR ROLLERS		/		

PART	S	WBS	SBOH	SBR
18 BALANCE WEIGHT SHOES		/		
19 CAR LANDING DOOR ACCESSORIES		/		
20 DOOR GEAR		/		
21 PUSHES & INDICATORS		/		
22 WORM & SPUR GEARING		/		
23 HOISTING MOTOR		/		
24 GENERATOR		/		
25 CONTROLLER CONTACTS		/		
26 WIRING		/		
27 BRAKE & BRAKE LININGS		/		
28 SELECTOR CONTACTS		/		
29 PULLEY WHEELS		/		
30 LIFT SHAFT SWITCHES		/		
31 RAM & CYLINDER		/		
32 VALVE GEAR		/		
33 RAM PACKINGS		/		
34 WHAT PARTS (IF ANY) INACCESSIBLE		/		

S = SATISFACTORY

WBS = WORN BUT SERVICEABLE

SBOH = SHOULD BE OVERHAULED

SBR = SHOULD BE RENEWED

TIME OF ARRIVAL _____

TIME OF DEPARTURE _____

OFFICE USE ONLY

MATERIALS

ROUTINE VISIT

ENGINEER'S REPORT / REMARKS / JHA

CUSTOMER'S SIGNATURE _____

ENGINEER'S SIGNATURE _____

Express House, 100 Rolt Street, Deptford, London SE8 5NN
Tel: _____ Fax: _____

ISO 9001
BUREAU VERITAS
Certification



CLB0244

PDR00000047/7

PDR00000047_0001



Lifts for London

ENGINEER SERVICE REPORT

Form No. 140/11 05/10

241679

EXPRESS
Lifts Alliance
Group

DATE 11/8/14

ENGINEER D. LANNY

SITE ADDRESS GREENFALL TOWER

CONTRACT No. P0807174

TYPE OF MACHINE TRACTION

No. OF MACHINE H090

PART	S	WBS	SBOH	SBR	PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY	/				18 BALANCE WEIGHT SHOES	/			
2 LANDING GATES OR DOORS	/				19 CAR LANDING DOOR ACCESSORIES	/			
3 CAR GATE(S) OR DOORS	/				20 DOOR GEAR	/			
4 LANDING GATE OR DOOR LOCKS	/				21 PUSHES & INDICATORS	/			
5 CAR GATE(S) OR DOOR LOCKS	/				22 WORM & SPUR GEARING	/			
6 OTHER GATE OR DOOR FASTENINGS	/				23 HOISTING MOTOR	/			
7 CAR OR PLATFORM FITTINGS	/				24 GENERATOR	/			
8 CAR GUIDES AND FITTINGS	/				25 CONTROLLER CONTACTS	/			
9 BUFFERS	/				26 WIRING	/			
10 OVER - RUNNING DEVICES	/				27 BRAKE & BRAKE LININGS	/			
11 SUSPENSION RODS	/				28 SELECTOR CONTACTS	/			
12 GOVERNOR ROPES	/				29 PULLEY WHEELS	/			
13 SAFETY ROPES	/				30 LIFT SHAFT SWITCHES	/			
14 SAFETY ROPES OR TAPES	/				31 RAM & CYLINDER	/			
15 SAFETY GEAR	/				32 VALVE GEAR	/			
16 OVERSPEED GOVERNOR CAR	/				33 RAM PACKINGS	/			
17 CAR SHOES OR ROLLERS	/				34 WHAT PARTS (IF ANY) INACCESSIBLE	/			

S = SATISFACTORY WBS = WORN BUT SERVICEABLE SBOH = SHOULD BE OVERHAULED SBR = SHOULD BE RENEWED

TIME OF ARRIVAL _____ TIME OF DEPARTURE _____

OFFICE USE ONLY

MATERIALS

ROUTINE VISIT

ENGINEER'S REPORT / REMARKS / JHA

CUSTOMER'S SIGNATURE _____

ENGINEER'S SIGNATURE 

Express House, 100 Rolt Street, Deptford, London SE8 5NN
Tel: _____ Fax: _____

ISO 9001
BUREAU VERITAS
Certification



CL80244



ENGINEER SERVICE REPORT

Form No. 140/11 05/10

259740

EXPRESS

Lifts Alliance
Group

Lifts for London

DATE

12/9/14

SITE ADDRESS

GREEN RELL TOWER

ENGINEER

D LUNBY

CONTRACT No.

P0807174

TYPE OF MACHINE

TRACTION

No. OF MACHINE

H090

PART	S	WBS	SBOH	SBR	PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY	/				18 BALANCE WEIGHT SHOES	/			
2 LANDING GATES OR DOORS	/				19 CAR LANDING DOOR ACCESSORIES	/			
3 CAR GATE(S) OR DOORS	/				20 DOOR GEAR	/			
4 LANDING GATE OR DOOR LOCKS	/				21 PUSHES & INDICATORS	/			
5 CAR GATE(S) OR DOOR LOCKS	/				22 WORM & SPUR GEARING	/			
6 OTHER GATE OR DOOR FASTENINGS	/				23 HOISTING MOTOR	/			
7 CAR OR PLATFORM FITTINGS	/				24 GENERATOR	/			
8 CAR GUIDES AND FITTINGS	/				25 CONTROLLER CONTACTS	/			
9 BUFFERS	/				26 WIRING	/			
10 OVER - RUNNING DEVICES	/				27 BRAKE & BRAKE LININGS	/			
11 SUSPENSION RODS	/				28 SELECTOR CONTACTS	/			
12 GOVERNOR ROPES	/				29 PULLEY WHEELS	/			
13 SAFETY ROPES	/				30 LIFT SHAFT SWITCHES	/			
14 SAFETY ROPES OR TAPES	/				31 RAM & CYLINDER	/			
15 SAFETY GEAR	/				32 VALVE GEAR	/			
16 OVERSPEED GOVERNOR CAR	/				33 RAM PACKINGS	/			
17 CAR SHOES OR ROLLERS	/				34 WHAT PARTS (IF ANY) INACCESSIBLE	/			

S = SATISFACTORY

WBS = WORN BUT SERVICEABLE

SBOH = SHOULD BE OVERHAULED

SBR = SHOULD BE RENEWED

TIME OF ARRIVAL

TIME OF DEPARTURE

OFFICE USE ONLY

MATERIALS

ROUTINE VISIT

ENGINEER'S REPORT / REMARKS / JHA

CUSTOMER'S SIGNATURE

ENGINEER'S SIGNATURE

Express House, 100 Rolt Street, Deptford, London SE8 5NN

Tel: [REDACTED] Fax: [REDACTED]

ISO 9001
BUREAU VERITAS
Certification



CL80244

PDR00000047/9

PDR00000047_0009



ENGINEER SERVICE REPORT

Form No. 140/11 05/10

258102
EXPRESS
Lifts Alliance
Group

Lifts for London

DATE 7/10/14

ENGINEER D. Linnig

SITE ADDRESS GRENFELL TOWER

CONTRACT No. PD807174

TYPE OF MACHINE TRACTION

No. OF MACHINE H 90

PART	S	WBS	SBOH	SBR	PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY	/				18 BALANCE WEIGHT SHOES	/			
2 LANDING GATES OR DOORS	/				19 CAR LANDING DOOR ACCESSORIES	/			
3 CAR GATE(S) OR DOORS	/				20 DOOR GEAR	/			
4 LANDING GATE OR DOOR LOCKS	/				21 PUSHES & INDICATORS	/			
5 CAR GATE(S) OR DOOR LOCKS	/				22 WORM & SPUR GEARING	/			
6 OTHER GATE OR DOOR FASTENINGS	/				23 HOISTING MOTOR	/			
7 CAR OR PLATFORM FITTINGS	/				24 GENERATOR	/			
8 CAR GUIDES AND FITTINGS	/				25 CONTROLLER CONTACTS	/			
9 BUFFERS	/				26 WIRING	/			
10 OVER - RUNNING DEVICES	/				27 BRAKE & BRAKE LININGS	/			
11 SUSPENSION RODS	/				28 SELECTOR CONTACTS	/			
12 GOVERNOR ROPES	/				29 PULLEY WHEELS	/			
13 SAFETY ROPES	/				30 LIFT SHAFT SWITCHES	/			
14 SAFETY ROPES OR TAPES	/				31 RAM & CYLINDER	/			
15 SAFETY GEAR	/				32 VALVE GEAR	/			
16 OVERSPEED GOVERNOR CAR	/				33 RAM PACKINGS	/			
17 CAR SHOES OR ROLLERS	/				34 WHAT PARTS (IF ANY) INACCESSIBLE	/			

S = SATISFACTORY

WBS = WORN BUT SERVICEABLE

SBOH = SHOULD BE OVERHAULED

SBR = SHOULD BE RENEWED

TIME OF ARRIVAL _____ TIME OF DEPARTURE _____

OFFICE USE ONLY

MATERIALS

ROUTINE VISIT

RECOMMENDS SHAFT + MOTOR ROOM CLEAN
DOWN AFTER BUILDING WORK.

ENGINEER'S REPORT / REMARKS / JHA

CUSTOMER'S SIGNATURE _____


ENGINEER'S SIGNATURE _____

Express House, 100 Rolt Street, Deptford, London SE8 5NN
Tel: [REDACTED] Fax: [REDACTED]

ISO 9001
BUREAU VERITAS
Certification



CL80244



Lifts for London

ENGINEER SERVICE REPORT

Form No. 140/11 05/10

256021

EXPRESS

Lifts Alliance Group

DATE 24-11-14

ENGINEER T.F. WILLIAMS

SITE ADDRESS GRENFEL TOWER

CONTRACT No. PD807174

W11 1TG

TYPE OF MACHINE PAS-TRAC

No. OF MACHINE H090

PART	S	WBS	SBOH	SBR	PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY		/			18 BALANCE WEIGHT SHOES		/		
2 LANDING GATES OR DOORS		/			19 CAR LANDING DOOR ACCESSORIES		/		
3 CAR GATE(S) OR DOORS		/			20 DOOR GEAR		/		
4 LANDING GATE OR DOOR LOCKS		/			21 PUSHES & INDICATORS		/		
5 CAR GATE(S) OR DOOR LOCKS		/			22 WORM & SPUR GEARING		/		
6 OTHER GATE OR DOOR FASTENINGS		/			23 HOISTING MOTOR		/		
7 CAR OR PLATFORM FITTINGS		/			24 GENERATOR		/		
8 CAR GUIDES AND FITTINGS		/			25 CONTROLLER CONTACTS		/		
9 BUFFERS		/			26 WIRING		/		
10 OVER - RUNNING DEVICES		/			27 BRAKE & BRAKE LININGS		/		
11 SUSPENSION RODS		/			28 SELECTOR CONTACTS		/		
12 GOVERNOR ROPES		/			29 PULLEY WHEELS		/		
13 SAFETY ROPES		/			30 LIFT SHAFT SWITCHES		/		
14 SAFETY ROPES OR TAPES		/			31 RAM & CYLINDER		/		
15 SAFETY GEAR		/			32 VALVE GEAR		/		
16 OVERSPEED GOVERNOR CAR		/			33 RAM PACKINGS		/		
17 CAR SHOES OR ROLLERS		/			34 WHAT PARTS (IF ANY) INACCESSIBLE		/		

S = SATISFACTORY WBS = WORN BUT SERVICEABLE SBOH = SHOULD BE OVERHAULED SBR = SHOULD BE RENEWED

TIME OF ARRIVAL _____ TIME OF DEPARTURE _____

OFFICE USE ONLY

MATERIALS

ENGINEER'S REPORT / REMARKS / JHA

RECOMMEND MOTOR ROOM AND SHAFT
CLEAN DOWN DUE TO BUILDERS ON SITE

CUSTOMER'S SIGNATURE _____

ENGINEER'S SIGNATURE T.F. Williams

Express House, 100 Rolt Street, Deptford, London SE8 5NN

Tel: _____ Fax: _____



CL80244



Lifts for London

ENGINEER SERVICE REPORT

Form No. 140/11 05/10

256094
250094

EXPRESS
Lifts Alliance
Group

DATE 19/12/14 ENGINEER S. HAGGARTY
SITE ADDRESS Grenfell Tower CONTRACT No. PD807174
TYPE OF MACHINE Traction
No. OF MACHINE H090

PART	S	WBS	SBOH	SBR	PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY	/				18 BALANCE WEIGHT SHOES	/			
2 LANDING GATES OR DOORS	/				19 CAR LANDING DOOR ACCESSORIES	/			
3 CAR GATE(S) OR DOORS	/				20 DOOR GEAR	/			
4 LANDING GATE OR DOOR LOCKS	/				21 PUSHES & INDICATORS	/			
5 CAR GATE(S) OR DOOR LOCKS	/				22 WORM & SPUR GEARING	/			
6 OTHER GATE OR DOOR FASTENINGS	/				23 HOISTING MOTOR	/			
7 CAR OR PLATFORM FITTINGS	/				24 GENERATOR	/			
8 CAR GUIDES AND FITTINGS	/				25 CONTROLLER CONTACTS	/			
9 BUFFERS	/				26 WIRING	/			
10 OVER - RUNNING DEVICES	/				27 BRAKE & BRAKE LININGS	/			
11 SUSPENSION RODS	/				28 SELECTOR CONTACTS	/			
12 GOVERNOR ROPES	/				29 PULLEY WHEELS	/			
13 SAFETY ROPES	/				30 LIFT SHAFT SWITCHES	/			
14 SAFETY ROPES OR TAPES	/				31 RAM & CYLINDER	/			
15 SAFETY GEAR	/				32 VALVE GEAR	/			
16 OVERSPEED GOVERNOR CAR	/				33 RAM PACKINGS	/			
17 CAR SHOES OR ROLLERS	/				34 WHAT PARTS (IF ANY) INACCESSIBLE	/			

S = SATISFACTORY

WBS = WORN BUT SERVICEABLE

SBOH = SHOULD BE OVERHAULED

SBR = SHOULD BE RENEWED

TIME OF ARRIVAL _____ TIME OF DEPARTURE _____

OFFICE USE ONLY

MATERIALS

ENGINEER'S REPORT / REMARKS / JHA

Short clean down req. after major building works. Severely dusty. Gear is leaking oil and requires attention

CUSTOMER'S SIGNATURE _____ ENGINEER'S SIGNATURE [Signature]

Express House, 100 Roit Street, Deptford, London SE8 5NN
Tel: _____ Fax: _____



CL80244



Lifts for London

ENGINEER SERVICE REPORT

Form No. 140/11 05/10

255566
255566

EXPRESS
Lifts Alliance
Group

DATE 31/1/15 ENGINEER S. Haggarty
SITE ADDRESS Greenfell Tower CONTRACT No. D807174
TYPE OF MACHINE Traction
No. OF MACHINE 14090

PART	S	WBS	SBOH	SBR	PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY	/				18 BALANCE WEIGHT SHOES	/			
2 LANDING GATES OR DOORS	/				19 CAR LANDING DOOR ACCESSORIES	/			
3 CAR GATE(S) OR DOORS	/				20 DOOR GEAR	/			
4 LANDING GATE OR DOOR LOCKS	/				21 PUSHES & INDICATORS	/			
5 CAR GATE(S) OR DOOR LOCKS	/				22 WORM & SPUR GEARING	/			
6 OTHER GATE OR DOOR FASTENINGS	/				23 HOISTING MOTOR	/			
7 CAR OR PLATFORM FITTINGS	/				24 GENERATOR	/			
8 CAR GUIDES AND FITTINGS	/				25 CONTROLLER CONTACTS	/			
9 BUFFERS	/				26 WIRING	/			
10 OVER - RUNNING DEVICES	/				27 BRAKE & BRAKE LININGS	/			
11 SUSPENSION RODS	/				28 SELECTOR CONTACTS	/			
12 GOVERNOR ROPES	/				29 PULLEY WHEELS	/			
13 SAFETY ROPES	/				30 LIFT SHAFT SWITCHES	/			
14 SAFETY ROPES OR TAPES	/				31 RAM & CYLINDER	/			
15 SAFETY GEAR	/				32 VALVE GEAR	/			
16 OVERSPEED GOVERNOR CAR	/				33 RAM PACKINGS	/			
17 CAR SHOES OR ROLLERS	/				34 WHAT PARTS (IF ANY) INACCESSIBLE	/			

S = SATISFACTORY WBS = WORN BUT SERVICEABLE SBOH = SHOULD BE OVERHAULED SBR = SHOULD BE RENEWED

TIME OF ARRIVAL _____ TIME OF DEPARTURE _____ OFFICE USE ONLY

MATERIALS

ENGINEER'S REPORT / REMARKS / JHA

Traces of oil around gear. Reseal is recommended. Full shaft clean down required due to ongoing building work.

CUSTOMER'S SIGNATURE _____ ENGINEER'S SIGNATURE S. Haggarty

Express House, 100 Rolt Street, Deptford, London SE8 5NN
Tel: _____ Fax: _____



CL80244



ENGINEER SERVICE REPORT

Form No. 140/11 05/10

256488

200708

EXPRESS

Lifts Alliance Group

Lifts for London

DATE 28/2/15 ENGINEER SHAGGAMTY
 SITE ADDRESS GLENFELK CONTRACT No. PD807174
 TYPE OF MACHINE TRACTION
 No. OF MACHINE 4090

PART	S	WBS	SBOH	SBR	PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY	/	/	/	/	18 BALANCE WEIGHT SHOES	/	/	/	/
2 LANDING GATES OR DOORS	/	/	/	/	19 CAR LANDING DOOR ACCESSORIES	/	/	/	/
3 CAR GATE(S) OR DOORS	/	/	/	/	20 DOOR GEAR	/	/	/	/
4 LANDING GATE OR DOOR LOCKS	/	/	/	/	21 PUSHES & INDICATORS	/	/	/	/
5 CAR GATE(S) OR DOOR LOCKS	/	/	/	/	22 WORM & SPUR GEARING	/	/	/	/
6 OTHER GATE OR DOOR FASTENINGS	/	/	/	/	23 HOISTING MOTOR	/	/	/	/
7 CAR OR PLATFORM FITTINGS	/	/	/	/	24 GENERATOR	/	/	/	/
8 CAR GUIDES AND FITTINGS	/	/	/	/	25 CONTROLLER CONTACTS	/	/	/	/
9 BUFFERS	/	/	/	/	26 WIRING	/	/	/	/
10 OVER-RUNNING DEVICES	/	/	/	/	27 BRAKE & BRAKE LININGS	/	/	/	/
11 SUSPENSION RODS	/	/	/	/	28 SELECTOR CONTACTS	/	/	/	/
12 GOVERNOR ROPES	/	/	/	/	29 PULLEY WHEELS	/	/	/	/
13 SAFETY ROPES	/	/	/	/	30 LIFT SHAFT SWITCHES	/	/	/	/
14 SAFETY ROPES OR TAPES	/	/	/	/	31 RAM & CYLINDER	/	/	/	/
15 SAFETY GEAR	/	/	/	/	32 VALVE GEAR	/	/	/	/
16 OVERSPEED GOVERNOR CAR	/	/	/	/	33 RAM PACKINGS	/	/	/	/
17 CAR SHOES OR ROLLERS	/	/	/	/	34 WHAT PARTS (IF ANY) INACCESSIBLE	/	/	/	/

S = SATISFACTORY WBS = WORN BUT SERVICEABLE SBOH = SHOULD BE OVERHAULED SBR = SHOULD BE RENEWED

TIME OF ARRIVAL _____ TIME OF DEPARTURE _____

OFFICE USE ONLY

MATERIALS

Builders have been on site for sometime.
 Full shaft clean down is required once
 works are complete.

ENGINEER'S REPORT / REMARKS / JHA

Repairs needed to check
 seals on gear box.

CUSTOMER'S SIGNATURE _____ ENGINEER'S SIGNATURE [Signature]

Express House, 100 Rolt Street, Deptford, London SE8 5NN
 Tel: _____ Fax: _____



CL80244



ENGINEER SERVICE REPORT

252730

EXPRESS
Lifts Alliance
Group

Lifts for London

DATE 25/4/15 ENGINEER S Haggarty
SITE ADDRESS Greenfell Twn CONTRACT No. PD607174
TYPE OF MACHINE Traction
No. OF MACHINE H090

PART	S	WBS	SBOH	SBR	PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY	/				18 BALANCE WEIGHT SHOES	/			
2 LANDING GATES OR DOORS	/				19 CAR LANDING DOOR ACCESSORIES	/			
3 CAR GATE(S) OR DOORS	/				20 DOOR GEAR	/			
4 LANDING GATE OR DOOR LOCKS	/				21 PUSHES & INDICATORS	/			
5 CAR GATE(S) OR DOOR LOCKS	/				22 WORM & SPUR GEARING	/			
6 OTHER GATE OR DOOR FASTENINGS	/				23 HOISTING MOTOR	/			
7 CAR OR PLATFORM FITTINGS	/				24 GENERATOR	/			
8 CAR GUIDES AND FITTINGS	/				25 CONTROLLER CONTACTS	/			
9 BUFFERS	/				26 WIRING	/			
10 OVER - RUNNING DEVICES	/				27 BRAKE & BRAKE LININGS	/			
11 SUSPENSION RODS	/				28 SELECTOR CONTACTS	/			
12 GOVERNOR ROPES	/				29 PULLEY WHEELS	/			
13 SAFETY ROPES	/				30 LIFT SHAFT SWITCHES	/			
14 SAFETY ROPES OR TAPES	/				31 RAM & CYLINDER	/			
15 SAFETY GEAR	/				32 VALVE GEAR	/			
16 OVERSPEED GOVERNOR CAR	/				33 RAM PACKINGS	/			
17 CAR SHOES OR ROLLERS	/				34 WHAT PARTS (IF ANY) INACCESSIBLE	/			

S = SATISFACTORY WBS = WORN BUT SERVICEABLE SBOH = SHOULD BE OVERHAULED SBR = SHOULD BE RENEWED

TIME OF ARRIVAL _____ TIME OF DEPARTURE _____ OFFICE USE ONLY

MATERIALS

Shaft clean down ~~strongly~~ required once
builders have finished works

ENGINEER'S REPORT / REMARKS / JHA

Gear seal's need investigating by repair

CUSTOMER'S SIGNATURE _____ ENGINEER'S SIGNATURE S Haggarty

Express House, 100 Rolt Street, Deptford, London SE8 5NN
Tel: _____ Fax: _____



CL80244



Lifts for London

ENGINEER SERVICE REPORT

Form No. 140/11 05/10

251928

EXPRESS
Lifts Alliance
Group

DATE 22/5/15 ENGINEER S. Haggarty
SITE ADDRESS Grenfell Tower CONTRACT No. PD807174
TYPE OF MACHINE Traction
No. OF MACHINE H090

PART	S	WBS	SBOH	SBR	PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY	/				18 BALANCE WEIGHT SHOES	/			
2 LANDING GATES OR DOORS	/				19 CAR LANDING DOOR ACCESSORIES	/			
3 CAR GATE(S) OR DOORS	/				20 DOOR GEAR	/			
4 LANDING GATE OR DOOR LOCKS	/				21 PUSHES & INDICATORS	/			
5 CAR GATE(S) OR DOOR LOCKS	/				22 WORM & SPUR GEARING	/			
6 OTHER GATE OR DOOR FASTENINGS	/				23 HOISTING MOTOR	/			
7 CAR OR PLATFORM FITTINGS	/				24 GENERATOR	/			
8 CAR GUIDES AND FITTINGS	/				25 CONTROLLER CONTACTS	/			
9 BUFFERS	/				26 WIRING	/			
10 OVER - RUNNING DEVICES	/				27 BRAKE & BRAKE LININGS	/			
11 SUSPENSION RODS	/				28 SELECTOR CONTACTS	/			
12 GOVERNOR ROPES	/				29 PULLEY WHEELS	/			
13 SAFETY ROPES	/				30 LIFT SHAFT SWITCHES	/			
14 SAFETY ROPES OR TAPES	/				31 RAM & CYLINDER	/			
15 SAFETY GEAR	/				32 VALVE GEAR	/			
16 OVERSPEED GOVERNOR CAR	/				33 RAM PACKINGS	/			
17 CAR SHOES OR ROLLERS	/				34 WHAT PARTS (IF ANY) INACCESSIBLE	/			

S = SATISFACTORY WBS = WORN BUT SERVICEABLE SBOH = SHOULD BE OVERHAULED SBR = SHOULD BE RENEWED

TIME OF ARRIVAL _____ TIME OF DEPARTURE _____

OFFICE USE ONLY

MATERIALS

Full shaft clean down is required after constant building works.

ENGINEER'S REPORT / REMARKS / JHA

Re seal on gen is required due to leakage.
Follow up is required for inspection

CUSTOMER'S SIGNATURE _____

ENGINEER'S SIGNATURE S. Haggarty

Express House, 100 Rolt Street, Deptford, London SE8 5NN
Tel: _____ Fax: _____

ISO 9001
BUREAU VERITAS
Certification



CL80244



Lifts for London

ENGINEER SERVICE REPORT

Form No. 140/11 05/10

255598

EXPRESS
Lifts Alliance
Group

DATE 25/6/12 ENGINEER S. Raggaby
SITE ADDRESS Greenwich Tower CONTRACT No. PD 807174
TYPE OF MACHINE Traction
No. OF MACHINE H090

PART	S	WBS	SBOH	SBR	PART	S	WBS	SBOH	SBR
1 ENCLOSURE OF HOISTWAY OR LIFTWAY	/	/	/	/	18 BALANCE WEIGHT SHOES	/	/	/	/
2 LANDING GATES OR DOORS	/	/	/	/	19 CAR LANDING DOOR ACCESSORIES	/	/	/	/
3 CAR GATES(S) OR DOORS	/	/	/	/	20 DOOR GEAR	/	/	/	/
4 LANDING GATE OR DOOR LOCKS	/	/	/	/	21 PUSHES & INDICATORS	/	/	/	/
5 CAR GATES(S) OR DOOR LOCKS	/	/	/	/	22 WORM & SPUR GEARING	/	/	/	/
6 OTHER GATE OR DOOR FASTENINGS	/	/	/	/	23 HOISTING MOTOR	/	/	/	/
7 CAR OR PLATFORM FITTINGS	/	/	/	/	24 GENERATOR	/	/	/	/
8 CAR GUIDES AND FITTINGS	/	/	/	/	25 CONTROLLER CONTACTS	/	/	/	/
9 BUFFERS	/	/	/	/	26 WIRING	/	/	/	/
10 OVER - RUNNING DEVICES	/	/	/	/	27 BRAKE & BRAKE LININGS	/	/	/	/
11 SUSPENSION RODS	/	/	/	/	28 SELECTOR CONTACTS	/	/	/	/
12 GOVERNOR ROPES	/	/	/	/	29 PULLEY WHEELS	/	/	/	/
13 SAFETY ROPES	/	/	/	/	30 LIFT SHAFT SWITCHES	/	/	/	/
14 SAFETY ROPES OR TAPES	/	/	/	/	31 RAM & CYLINDER	/	/	/	/
15 SAFETY GEAR	/	/	/	/	32 VALVE GEAR	/	/	/	/
16 OVERSPEED GOVERNOR CAR	/	/	/	/	33 RAM PACKINGS	/	/	/	/
17 CAR SHOES OR ROLLERS	/	/	/	/	34 WHAT PARTS (IF ANY) INACCESSIBLE	/	/	/	/

S = SATISFACTORY WBS = WORN BUT SERVICEABLE SBOH = SHOULD BE OVERHAULED SBR = SHOULD BE RENEWED

TIME OF ARRIVAL _____ TIME OF DEPARTURE _____

OFFICE USE ONLY

MATERIALS

Gear box leaking. Investigation req.

Shaft clean down needed once builders are off site

ENGINEER'S REPORT / REMARKS / JHA

CUSTOMER'S SIGNATURE _____

ENGINEER'S SIGNATURE [Signature]

Express House, 100 Rolt Street, Deptford, London SE8 5NN
Tel: _____ Fax: _____



CL80244

EXPRESS

Service Visit Report

ISO 9001
BUREAU VERITAS
Certification



Lifts Alliance Group

Registered in London No. 147366 and Jersey No. 0008376
Registered Office, Chiswick Park Building 5, Ground Floor, 566 Chiswick High Road, W4 5YF

Service and breakdown
London & South East: [REDACTED]
All Other UK Regions: [REDACTED]

Visit Type M
Unit Number PD807174
Customer Order No.
Site Address

CALLBACK/REPAIR No.
Misuse (Y/N) ☐ Completed (Y/N) ☐
Accidental Damage (Y/N) ☐ Shutdown (Y/N) ☐

GLENEEL TOWER

Unit Type/Customer Unit Reference H090 Customer Name TMO

Maintenance Activity Report (✓ as applicable)

	Checked		Serviceable	
	Y	Not Fitted	Y	N
Car Operating Panel/s	✓		✓	
Car Lighting	✓		✓	
Emergency Alarm Systems	✓		✓	
Hall Buttons / Indicators	✓		✓	
Floor Levels	✓		✓	
Controller / Drive	✓		✓	
Brake	✓		✓	
Machine / Hydro Power Unit	✓		✓	
Overspeed Devices	✓		✓	
Operation of Car Doors	✓		✓	
Car Top	✓		✓	

	Checked		Serviceable	
	Y	Not Fitted	Y	N
Landing Doors	✓		✓	
Counterweight / RAM	✓		✓	
Main Suspension Check	✓		✓	
Pit Area	✓		✓	
Annual / 4 Year Checks				
Door Check				
Suspension Check				
RA Review				
Elec & Mech Check				
Earth Continuity Test				
Brake Check				

Scope of Work & Materials Used (quoting part number where possible)

Observations

BUILDERS ON SITE, FULL SHAFT CLEAN DOWN REQUIRED ONCE WORKS ARE COMPLETE

	Engineer's Name (Please print clearly)	Employee Number	Arrival Time	Depart Time	Total Site Hours	Travel Hours
Engineer 1	S. HACCARTY	58388	:	:	:	:
Engineer 2	T. WILLIAMS	58512	:	:	:	:

Date:	Customer's Name:	Customer's Signature:
-------	------------------	-----------------------

Top Copy: Customer Second Copy: Office

78.9.49.477(03.14)

Lifts Alliance
GroupRegistered in London No. 147366 and Jersey No. 0008376
Registered Office, Chiswick Park Building 5, Ground Floor, 566 Chiswick High Road, W4 5YFService and breakdown
London & South East: [REDACTED]
All Other UK Regions: [REDACTED]Visit Type M
Unit Number PD807174
Customer Order No.
Site Address
GRENFELLCALLBACK/REPAIR No.
Misuse (Y / N) ☐ Completed (Y / N) ☐
Accidental Damage (Y / N) ☐ Shutdown (Y / N) ☐Unit Type/Customer Unit Reference H090 Customer Name TMO

Maintenance Activity Report (✓ as applicable)

	Checked		Serviceable	
	Y	Not Fitted	Y	N
Car Operating Panel/s	✓		✓	
Car Lighting	✓		✓	
Emergency Alarm Systems	✓		✓	
Hall Buttons / Indicators	✓		✓	
Floor Levels	✓		✓	
Controller / Drive	✓		✓	
Brake	✓		✓	
Machine / Hydro Power Unit	✓		✓	
Overspeed Devices	✓		✓	
Operation of Car Doors	✓		✓	
Car Top	✓		✓	

	Checked		Serviceable	
	Y	Not Fitted	Y	N
Landing Doors	✓		✓	
Counterweight / RAM	✓		✓	
Main Suspension Check	✓		✓	
Pit Area	✓		✓	
Annual / 4 Year Checks				
Door Check				
Suspension Check				
RA Review				
Elec & Mech Check				
Earth Continuity Test				
Brake Check				

Scope of Work & Materials Used (quoting part number where possible)

Observations

Short clean down required once builders have finished works

	Engineer's Name (Please print clearly)	Employee Number	Arrival Time	Depart Time	Total Site Hours	Travel Hours
Engineer 1	S. HAGGARTY	58388	:	:	:	:
Engineer 2	T. WILLIAMS	58512	:	:	:	:

Date: 20/08/15	Customer's Name:	Customer's Signature:
-------------------	------------------	-----------------------

Top Copy: Customer Second Copy: Office

78.5.49.477(03.14)



Service Visit Report



Lifts Alliance Group

Registered in London No. 147366 and Jersey No. 0008376
Registered Office, Chiswick Park Building 5, Ground Floor, 566 Chiswick High Road, W4 5YF

Service and breakdown
London & South East: [redacted]
All Other UK Regions: [redacted]

Visit Type
Unit Number
Customer Order No.

CALLBACK/REPAIR No.
Misuse (Y / N) ☐ Completed (Y / N) ☐
Accidental Damage (Y / N) ☐ Shutdown (Y / N) ☐

Site Address

GLENFELL TOWER

Unit Type/Customer Unit Reference

Customer Name

Maintenance Activity Report (✓ as applicable)

	Checked		Serviceable	
	Y	Not Fitted	Y	N
Car Operating Panel/s	✓		✓	
Car Lighting	✓		✓	
Emergency Alarm Systems	✓		✓	
Hall Buttons / Indicators	✓		✓	
Floor Levels	✓		✓	
Controller / Drive	✓		✓	
Brake	✓		✓	
Machine / Hydro Power Unit	✓		✓	
Overspeed Devices	✓		✓	
Operation of Car Doors	✓		✓	
Car Top	✓		✓	

	Checked		Serviceable	
	Y	Not Fitted	Y	N
Landing Doors	✓		✓	
Counterweight / RAM	✓		✓	
Main Suspension Check	✓		✓	
Pit Area	✓		✓	
Annual / 4 Year Checks				
Door Check				
Suspension Check				
RA Review				
Elec & Mech Check				
Earth Continuity Test				
Brake Check				

Scope of Work & Materials Used (quoting part number where possible)

[Empty box for Scope of Work & Materials Used]

Observations

Full shaft clean down required once builders have finished works.
Oil seals require investigation due to leaks

	Engineer's Name (Please print clearly)	Employee Number	Arrival Time	Depart Time	Total Site Hours	Travel Hours
Engineer 1	S. HAGGARTY	S 8388	:	:	:	:
Engineer 2	T. WILLIAMS	S 8512	:	:	:	:

Date: 25/9/15
Customer's Name: [redacted]
Customer's Signature: [redacted]

Top Copy: Customer Second Copy: Office

78.9.49.477(05.14)

Job Number	PD807174
Unit Number	PD807174
Site Address	Grenfell Tower Grenfell Road London W11 1TG
Unit Reference	H090
Date of Service Visit Report	04/11/2015
Visit Type	M2

Customer Order Number	
Parts Used	

Works Completed
As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :
<ul style="list-style-type: none"> Car Enclosure and COP Emergency Alarm System Indicators and Call Buttons Floor Levels and Selector Machine and Brake Controller and Drive Overspeed Devices Operation of Car Doors Car Top Door and Gate Check Shaft Equipment Pit and Underside of Car Annual Main Suspension Check Annual Door Check Electrical Safety Switch Check Annual Brake Check

Observations
full shaft cleandown requied once builders have completed works seals leaking slightly on gear

Total Time on Site	1.30
Total Travel to Site	0.00

Customer Name	Customer Unavailable For Signature
Signed Date & Time	

Signature Declined	N
Decline Reason	

Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
S Haggarty (58388)	28/10/15	11:00	12:30	1.30	0.00	N/A

ELA Group
A division of Otis Ltd, registered in England and Wales, No 147366
Registered Office: Chiswick Park, Building 5 Ground Floor, 566 Chiswick High Road, London W4 5YF

Job Number PD807174

Unit Number PD807174

Site Address
Grenfell Tower
Grenfell Road
London W11 1TG

Unit Reference H090

Date of Service Visit Report 27/01/2016

Visit Type M2

Works Completed

As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :

Car Enclosure and COP
Emergency Alarm System
Indicators and Call Buttons
Floor Levels and Selector
Machine and Brake
Controller and Drive
Overspeed Devices
Operation of Car Doors
Car Top
Door and Gate Check
Shaft Equipment
Pit and Underside of Car

Signature Declined N

Decline Reason

Attending Engineer(s)

Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
S Haggarty (58388)	25/01/16	08:00	09:15	1.15	0.00	N/A

ELA Group
A division of Otis Ltd registered in England and Wales, No 147366
Registered Office: Chiswick Park, Building 5 Ground Floor, 566 Chiswick High Road, London W4 5YF

Customer Order Number

Parts Used

Observations

full shaft cleandown requied once builders have completed works seals leaking slightly on gear door operator needs setting up once builders have completed works still no phonline in lift

Total Time on Site 1.15

Total Travel to Site 0.00

Customer Name

Signed Date & Time

**Customer
Unavailable
For Signature**

Job Number	PD807174
Unit Number	PD807174
Site Address	Grenfell Tower Grenfell Road London W11 1TG
Unit Reference	H090
Date of Service Visit Report	25/02/2016
Visit Type	S

Customer Order Number	
Parts Used	

Works Completed
As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :
<ul style="list-style-type: none"> Car Enclosure and COP Emergency Alarm System Indicators and Call Buttons Floor Levels and Selector Machine and Brake Controller and Drive Overspeed Devices Operation of Car Doors Car Top Door and Gate Check Shaft Equipment Pit and Underside of Car Annual Main Suspension Check Annual Door Check Electrical Safety Switch Check Annual Brake Check

Observations
full shaft cleandown requied once builders have completed works seals leaking slightly on gear door operator needs setting up once builders have completed works still no phoneline in lift

Total Time on Site	1.30
--------------------	------

Total Travel to Site	0.00
----------------------	------

Customer Name	Customer Unavailable For Signature
Signed Date & Time	

Signature Declined	N
Decline Reason	

Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
S Haggarty (58388)	19/02/16	08:00	09:30	1.30	0.00	N/A

Job Number PD807174

Unit Number PD807174

Site Address
Grenfell Tower
Grenfell Road
London W11 1TG

Unit Reference H090

Date of Service Visit Report 26/05/2016

Visit Type M2

Works Completed

As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :

Car Enclosure and COP
Emergency Alarm System
Indicators and Call Buttons
Floor Levels and Selector
Machine and Brake
Controller and Drive
Overspeed Devices
Operation of Car Doors
Car Top
Door and Gate Check
Shaft Equipment
Pit and Underside of Car

Customer Order Number

Parts Used

Observations

full shaft cleandown requied once builders have completed works. seals leaking slightly on gear. door operator needs setting up once builders have completed works. there is an earth on thr ground floor display which is blowing fuses in the psu2unit. contractors have glued display plate to wall and will create damage to wall. custmer action required

Total Time on Site 1.00

Total Travel to Site 0.00

Customer Name

Signed Date & Time

**Customer
Unavailable
For Signature**

Signature Declined N

Decline Reason

Attending Engineer(s)

Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
S Haggarty (58388)	25/05/16	10:00	11:00	1.00	0.00	N/A

Job Number PD807174

Unit Number PD807174

Site Address
Grenfell Tower
Grenfell Road
London W11 1TG

Unit Reference H090

Date of Service Visit Report 11/07/2016

Visit Type M2

Works Completed

As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :

Car Enclosure and COP
Emergency Alarm System
Indicators and Call Buttons
Floor Levels and Selector
Machine and Brake
Controller and Drive
Overspeed Devices
Operation of Car Doors
Car Top
Door and Gate Check
Shaft Equipment
Pit and Underside of Car

Signature Declined N

Decline Reason

Customer Order Number

Parts Used

Observations

full shaft cleandown required once builders have completed works. seals leaking slightly on gear. door operator needs setting up once builders have completed works. there is an earth on the ground floor display which is blowing fuses in the psu2unit. contractors have glued display plate to wall and will create damage to wall. customer action required

Total Time on Site 1.00

Total Travel to Site 0.00

Customer Name

Signed Date & Time

Customer
Unavailable
For Signature

Attending Engineer(s)

Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
S Haggarty (58388)	29/06/16	15:00	16:00	1.00	0.00	N/A

Job Number PD807174

Unit Number PD807174

Site Address
Grenfell Tower
Grenfell Road
London W11 1TG

Unit Reference H090

Date of Service Visit Report 18/10/2016

Visit Type M2

Works Completed

As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :

Car Enclosure and COP
Emergency Alarm System
Indicators and Call Buttons
Floor Levels and Selector
Machine and Brake
Operation of Car Doors
Car Top
Shaft Equipment

Signature Declined N

Decline Reason

Customer Order Number

Parts Used

Observations

full shaft cleandown required once builders have completed works. seals leaking slightly on gear. door operator needs setting up once builders have completed works. there is an earth on the ground floor display which is blowing fuses in the psu2unit. contractors have glued display plate to wall and will create damage to wall. customer action required new car door hanger rollers have been fitted. recommend car lighting and car fan have a separate feed

Total Time on Site 2.01

Total Travel to Site 0.00

Customer Name

Signed Date & Time

Customer
Unavailable
For Signature

Attending Engineer(s)

Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
D Smalley (55029)	18/10/16	08:00	10:01	2.01	0.00	N/A

Job Number	PD807174
Unit Number	PD807174
Site Address	Grenfell Tower Grenfell Road London W11 1TG
Unit Reference	H090
Date of Service Visit Report	19/12/2016
Visit Type	M2

Customer Order Number	
Parts Used	

<p>Works Completed</p> <p>As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :</p> <ul style="list-style-type: none"> Car Enclosure and COP Emergency Alarm System Indicators and Call Buttons Floor Levels and Selector Machine and Brake Operation of Car Doors Car Top Shaft Equipment
--

<p>Observations</p> <p>full shaft cleandown required once builders have completed works. seals leaking slightly on gear. door operator needs setting up once builders have completed works. there is an earth on the ground floor display which is blowing fuses in the psu2unit. contractors have glued display plate to wall and will create damage to wall. customer action required new car door hanger rollers have been fitted. recommend lg1 car lighting and car fan have a separate feed lg1 done nov visit</p>

Total Time on Site	1.45
--------------------	------

Total Travel to Site	0.15
----------------------	------

Customer Name	Customer Unavailable For Signature
Signed Date & Time	

Signature Declined	N
Decline Reason	

Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
D Smalley (55029)	19/12/16	12:15	14:00	1.45	0.15	N/A

Job Number PD807174

Unit Number PD807174

Site Address
Grenfell Tower
Grenfell Road
London W11 1TG

Unit Reference H090

Date of Service Visit Report 05/01/2017

Visit Type S

Works Completed

As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :

Car Enclosure and COP
Emergency Alarm System
Indicators and Call Buttons
Floor Levels and Selector
Machine and Brake
Operation of Car Doors
Car Top
Shaft Equipment

Signature Declined N

Decline Reason

Attending Engineer(s)

Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
D Smalley (55029)	05/01/17	08:00	10:00	2.00	0.00	N/A

ELA Group
A division of Otis Ltd registered in England and Wales, No 147366
Registered Office: Chiswick Park, Building 5 Ground Floor, 566 Chiswick High Road, London W4 5YF

Customer Order Number

Parts Used

Observations

full shaft cleandown requied once builders have completed works. seals leaking slightly on gear. door operator needs setting up once builders have completed works. there is an earth on thr ground floor display which is blowing fuses in the psu2unit. contractors have glued display plate to wall and will create damage to wall. custmer action required new car door hanger rollers have been fitted. recommend lg1 car lighting and car fan have a separate feed lg1 done nov visit dec visit

Total Time on Site 2.00

Total Travel to Site 0.00

Customer Name

Signed Date & Time

Customer
Unavailable
For Signature

Job Number	PD807174
Unit Number	PD807174
Site Address	Grenfell Tower Grenfell Road London W11 1TG
Unit Reference	H090
Date of Service Visit Report	18/01/2017
Visit Type	M2

Customer Order Number	
Parts Used	

Works Completed
As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :
<p>Car Enclosure and COP Emergency Alarm System Indicators and Call Buttons Floor Levels and Selector Machine and Brake Operation of Car Doors Car Top</p>

Observations
<p>full shaft cleandown requied once builders have completed works. seals leaking slightly on gear. door operator needs setting up once builders have completed works. there is an earth on thr ground floor display which is blowing fuses in the psu2unit. contractors have glued display plate to wall and will create damage to wall. customer action required new car door hanger rollers have been fitted. recommend lg1 car lighting and car fan have a separate feed lg1 done nov visit dec visit</p>

Total Time on Site	1.45
--------------------	------

Total Travel to Site	0.15
----------------------	------

Customer Name	Customer Unavailable For Signature
Signed Date & Time	

Signature Declined	N
Decline Reason	

Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
D Smalley (55029)	18/01/17	08:15	10:00	1.45	0.15	N/A

Job Number PD807174

Unit Number PD807174

Site Address
Grenfell Tower
Grenfell Road
London W11 1TG

Unit Reference H090

Date of Service Visit Report 20/02/2017

Visit Type S

Works Completed

As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :

Car Enclosure and COP
Emergency Alarm System
Indicators and Call Buttons
Floor Levels and Selector
Machine and Brake
Operation of Car Doors
Car Top
Shaft Equipment

Signature Declined N

Decline Reason

Customer Order Number

Parts Used

Observations

full shaft cleandown required once builders have completed works. seals leaking slightly on gear. door operator needs setting up once builders have completed works. there is an earth on thr ground floor display which is blowing fuses in the psu2unit. contractors have glued display plate to wall and will create damage to wall. customer action required new car door hanger rollers have been fitted. recommend lg1 car lighting and car fan have a separate feed lg1 done nov visit dec visit

Total Time on Site 1.45

Total Travel to Site 0.15

Customer Name

Signed Date & Time

**Customer
Unavailable
For Signature**

Attending Engineer(s)

Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
D Smalley (55029)	30/11/16	12:15	14:00	1.45	0.15	N/A

Job Number PD807174

Unit Number PD807174

Site Address
Grenfell Tower
Grenfell Road
London W11 1TG

Unit Reference H090

Date of Service Visit Report 08/03/2017

Visit Type M2

Works Completed

As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :

Car Enclosure and COP
Emergency Alarm System
Indicators and Call Buttons
Floor Levels and Selector
Machine and Brake
Operation of Car Doors
Car Top
Shaft Equipment
Pit and Underside of Car

Signature Declined N

Decline Reason

Attending Engineer(s)

Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
D Smalley (55029)	08/03/17	08:00	10:00	2.00	0.00	N/A

ELA Group
A division of Otis Ltd registered in England and Wales, No 147366
Registered Office: Chiswick Park, Building 5 Ground Floor, 566 Chiswick High Road, London W4 5YF

Customer Order Number

Parts Used

Observations

full shaft cleandown requied once builders have completed works. seals leaking slightly on gear. door operator needs setting up once builders have completed works. there is an earth on thr ground floor display which is blowing fuses in the psu2unit. contractors have glued display plate to wall and will create damage to wall. custmer action required new car door hanger rollers have been fitted. recommend lg1 car lighting and car fan have a separate feed lg1 done nov visit dec visit

Total Time on Site 2.00

Total Travel to Site 0.00

Customer Name

Signed Date & Time

**Customer
Unavailable
For Signature**

Job Number PD807174

Unit Number PD807174

Site Address
Grenfell Tower
Grenfell Road
London W11 1TG

Unit Reference H090

Date of Service Visit Report 20/03/2017

Visit Type M2

Works Completed

As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :

Car Enclosure and COP
Emergency Alarm System
Indicators and Call Buttons
Floor Levels and Selector
Machine and Brake
Controller and Drive
Overspeed Devices
Operation of Car Doors
Car Top
Door and Gate Check
Shaft Equipment
Pit and Underside of Car

Signature Declined N

Decline Reason

Customer Order Number

Parts Used

Observations

Total Time on Site 1.30

Total Travel to Site 0.00

Customer Name

Signed Date & Time

Customer
Unavailable
For Signature

Attending Engineer(s)

Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
T Parker (58461)	11/02/17	08:00	09:30	1.30	0.00	N/A

Job Number	PD807174
Unit Number	PD807174
Site Address	Grenfell Tower Grenfell Road London W11 1TG
Unit Reference	H090
Date of Service Visit Report	27/04/2017
Visit Type	M2

Customer Order Number	
Parts Used	

Works Completed
<p>As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :</p> <p>Car Enclosure and COP Emergency Alarm System Indicators and Call Buttons Floor Levels and Selector Machine and Brake Controller and Drive Overspeed Devices Operation of Car Doors Car Top Door and Gate Check Shaft Equipment Pit and Underside of Car</p>

Observations
<p>seals leaking slightly on gear. door operator needs setting up once builders have completed works. contractors have glued display plate to wall and will create damage to wall. customer action recommend lg1 car lighting and car fan have a separate feed lg1 done nov visit dec visit. unit requires pit ladder</p>

Total Time on Site	2.00
--------------------	------

Total Travel to Site	0.00
----------------------	------

Customer Name	Customer Unavailable For Signature
Signed Date & Time	

Signature Declined	N
Decline Reason	

Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
A Smart (58579)	12/04/17	10:00	12:00	2.00	0.00	N/A

Job Number	PD807174
Unit Number	PD807174
Site Address	Grenfell Tower Grenfell Road London W11 1TG
Unit Reference	H090
Date of Service Visit Report	31/05/2017
Visit Type	S

Customer Order Number	
Parts Used	

Works Completed
As part of the scheduled maintenance visit, the below items were checked by our engineer and found to be serviceable :
<ul style="list-style-type: none"> Car Enclosure and COP Emergency Alarm System Indicators and Call Buttons Floor Levels and Selector Machine and Brake Controller and Drive Overspeed Devices Operation of Car Doors Car Top Door and Gate Check Shaft Equipment Pit and Underside of Car

Observations
seals leaking slightly on gear. door operator needs setting up once builders have completed works. contractors have glued display plate to wall and will create damage to wall. customer action recommend lg1 car lighting and car fan have a separate feed lg1 done nov visit dec visit. unit requires pit ladder

Total Time on Site	2.00
---------------------------	------

Total Travel to Site	0.00
-----------------------------	------

Customer Name	Customer Unavailable For Signature
Signed Date & Time	

Signature Declined	N
Decline Reason	

Attending Engineer(s)						
Engineer Name	Date Attended	Site Arrival	Site Depart	Time on site	Travel to site	Customer Signoffs
A Smart (58579)	09/05/17	13:00	15:00	2.00	0.00	N/A