

**APPENDIX A12**

**EXHIBIT SCM/1: BELIEVED CAPACITOR (MELTED)**



**FIGURE A12 -1 & A12-2**

**EXHIBIT MJD/61: WIRING FROM WALL TO LEFT OF SINK**


**FIGURE A12 -3**



**Figure A12-1: SCM/1 – Capacitor Remains [J.D. Glover Photo – 26 September 2018]**



**Figure A12-2: X-Rays of SCM/1 and P2 Capacitor [J.D. Glover Photo – 21 September 2018]**



**Figure A12-3: MJD/61: Wiring from Wall to Left of Sink [J.D. Glover Photo – 21 September 2018]**